SURVEY & REMONUMENTATION

DEC 13 2000

LAND CORNER RECORDATION CERTIFICATE

SECTION

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

For corners in Osceola		L	ocated in:	Corner Code#					~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	. 9	⊋ ;	∞
1.	Public Land Survey	r	T 17 N	R 10 W	G-13			,	I ko Li	300	בי בי	
			<u>T</u>	R					K			
			T	R					i in	ა : =	9	유승
			<u>T</u>	R					100			
2.		; <u>s</u>	Т	R					8	-	i	SG
	in Section	s	<u>T</u>	R		Registe		مام م ما <i>م</i>	Cham	0 ["la Ni	
3.	Miscellaneous Property in Sec.	s		_ R		Registe	OIL	Jeeus	Stan	ip & r	ne m	umber
		S	Т	_R								
		rded Plat	at			A B C D E F G H I J K L M						
5. Private Claims							6	5	4	3	2	1
I, Robert L. Wetherell, in a field survey on <u>September 18, 2000</u> , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner							7	8	9	10	11	12
points mentioned in lines 1 and 2 above were in conformance with regulations and							18	Ť				
rules therefore as required in the current manual of survey instructions of the United								17	16	15	14	13
States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were							19	20	21	22	23	24
In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree												
Of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:							30	29	28	27	26	25
	,					11 12 13	31	32	33	34	35	36
G-13 - Section corner common to Sections 33 & 34, T17N, R10W. A. Description of original monument and accessories and/or subsequent restoration:												

1837 - J. Hodgson, G.L.O. #1 - 8" Elm N29°E 32 Links #2 - 8" Ironwood N50°W 45 Links Section corner for 3 & 4, Town 16 North, Range 10 West is 20 Links West.

1988 - D. Wood, LS 24625

L.C.R.C. - Liber 02, Pg. 292.

"Steel Bar in Mon. Box".

#3 - T. Pole N60°W 70.95'

#4 - P. Pole N25°E 129.85'

#5 - Corner fence post N50°E 54.10'

#6 - Corner fence post S45°E 56.35 centerline of road - West 2.00'

1991 - M. McClung, LS 13037

Survey recorded L. 595, Pg. 208. Same accessories as 1988 by Wood.

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found a ½" rod in a monument box 2 feet more or less East of the centerline of Old Highway 131. This corner fits 1/16 line occupation both East and West.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Found in good condition, #4 New Pole, #5 Found in good condition, #6 New Post.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I accepted the ½" iron in the monument box as a substantial marker for the corner, and is accepted as a careful and faithful reestablishment of the position of the original corner.

P. Pole N49°W 48.16' (Nail and Tag N. side) 20" Walnut S13°W 215.9' (center of tree) P. Pole S17°E 127.44' (P.K. nail E. side)

Geodetic Control Marker N71°E 81.58' (1/2" rod in box).

APPROVED LAND CORNER P.A. 345 OF 1990 Osceola County

7. Wethere Surveyor's Michigan License No. 24624

Date November 1, 2000

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983 ADAPTED FOR WORD PROCESSING JANUARY, 1999

aang