DEC 13 2000

SECTION

For corners in Osceola

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

Corner Code#

Located in:

1.	1. Public Land Survey		17 N					\c						
		T		R					-	13	8	Zi O		
		T	_	R					N		S S	338		
		 T		R					; }		2	HO A		
2.	Property Controlling	— т 8 г		R					2	i C	<u> </u>	유		
_,	in Section	<u> </u>							13		£	ME		
		<u>S</u> T		R		Register of Deeds Starting & File Number								
3.	Miscellaneous Property in Sec.	<u>s</u> <u>r</u>		R		<u>. </u>								
4	Lot NoReco	ST_		₹				G . D .		N W.				
		rded Plat				1	АВ		E F (; H	JE	LM		
1, F	Robert <u>L. Wetherell,</u> in a	ı field survey on <u>S</u>	eptembe	r 18, 2000,	do	2	6	5	4	3	2	1		
hereby certify that under requirements of P.A. 74, Michigan points mentioned in lines 1 and 2 above were in conformant						4 5	7	8	9	10	11	12		
rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a To be determined in the current manual of survey instructions of the United for the United fo										13				
Co	urt of Law and/or that th	he comer points n	nentioned	ntioned in lines 3, 4, and 5 above were Board of Land Surveyors or by a Decree			19	20	21	22	23	24		
Of a Court of Law; established, re-establish							30	29	28	27	26	25		
rec	overed, found as expre	ssed below:				11 12	31	32	33	34	35	36		
<u>K-</u> 3	K-13 - Section corner common to Sections 35 & 36, T17N, R10W, on S. Section line.													
Α.	A. Description of original monument and accessories and/or subsequent restoration:													
	1837 - J. Hodgson, G #1 - 8" Sugar N66°E							1983 - J. Pierson, LS 19307 #6 - Distance West = 2630.9'						
	#2 - 8" Beech N54°W	Undated Co Com Trem Book				#7 - Mecosta Co. Corner - East 8.7'								
	Corner common to Sections 1 & 2, Town 16 North, Range 10 West East 10 Links			Undated Co. Sur. Twp. Book "Iron".										
				#4 - 16" Maple N.W. 77' #5 - Fence Post N.E. 37½'										
D	B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:													
D.	•			•	`		_							
	I found a ½" re-bar over top of an old plow point. Corner is in the centerline of road East and West and 4 feet more or less West of centerline of roads North and South.													
Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Did not measure, #4 Gone, #5 Gone,														
#6 Measured 2631.0', #7 Measured 8.45'.														
C.	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:													
	I replaced the ½" rebar with a 1" x 18" Iron Pipe with an Osceola Co. Remon Cap, and is accepted as a careful and faithful reestablishment of the position of the original corner.													
		•			•					· ·		100		
	P. Pole N71°E 83.44′ 3″ Tw. Maple S31°W		ide)	,	VPPROVED LAND C	ODNED				المراجعة عال	. sandana	The same of the sa		
24" Cherry N4°W 250.19' (60d spike l 36" Maple N89°E 222.02' (60d spike s				·	P.A. 345 CF 190 Osceola County	90					` = 4! `}*(}			
			e S. side)		R & LO	f			- ;; X		ANNAN Marka	OH		
10-31-2000											10 Jan 101			
	Ro	+ 4 111	, , 1-4: .	-1 <i>1</i>	The state of the s	The second second			3. 3. 3. 5 Car	CO ,	e es es e	344		
Signed by Solert J. Wetherld Date November 1, 2000 Surveyor's Michigan License No. 24624												med a		
	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975													
						ADA	PTED F	OR WO	RD PRC			JAN. 1983 JARY, 1999		