SURVEY & REMONUMENTATION

FEB 1 6 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Oscaola County) 1. Public Land Survey T18NR 10W TR TR TR TR TR TR TR TR TR T	
TR R Scotion S T R S Scotion S T R S Scotion S T R S Scotion S S S T R S Scotion S S S T R S Scotion S S S S T R S Scotion S S S S S S S S S S S S S S S S S S S	
2. Property Controlling in Section S T R in Section S T R Property in Sec. S T R Property in Sec. S T R Property in Sec. S T R 4. Lot No. , Recorded Plat 5. Private Claims 1. Matthew McClungin a field survey on 4-18 , 19 98 do hereby state that under requirements of PA. 74. Michigan PA. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor John Hodgson on 10 June 1838. Set wood post 80.00 chains from South. Beech 9" N29W 12 1ks. Beech 9" S61E 32 1ks.	
I. Matthew McClungin a field survey on 4-18 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration. The original corner was set by deputy surveyor John Hodgson on 10 June 1838. Set wood post 80.00 chains from South. Beech 9" N29W 12 1ks. Beech 9" S61E 32 1ks.	nber
I. Matthew McClungin a field survey on 4-18 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration. The original corner was set by deputy surveyor John Hodgson on 10 June 1838. Set wood post 80.00 chains from South. Beech 9" N29W 12 1ks. Beech 9" S61E 32 1ks.	
I. Matthew McClungin a field survey on 4-18, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor John Hodgson on 10 June 1838. Set wood post 80.00 chains from South. Beech 9" N29W 12 1ks. Beech 9" S61E 32 1ks.	L
I. Matthew McClungin a field survey on 4-18, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor John Hodgson on 10 June 1838. Set wood post 80.00 chains from South. Beech 9" N29W 12 lks. Beech 9" S61E 32 lks.	
A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor John Hodgson on 10 June 1838. Set wood post 80.00 chains from South. Beech 9" N29W 12 lks. Beech 9" S61E 32 lks.	—12- —13- —24-
A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor John Hodgson on 10 June 1838. Set wood post 80.00 chains from South. Beech 9" N29W 12 lks. Beech 9" S61E 32 lks.	+
A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor John Hodgson on 10 June 1838. Set wood post 80.00 chains from South. Beech 9" N29W 12 lks. Beech 9" S61E 32 lks.	 25-
A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor John Hodgson on 10 June 1838. Set wood post 80.00 chains from South. Beech 9" N29W 12 lks. Beech 9" S61E 32 lks.	 36-
Page 3, Calls for iron. Elm 6" NE 62.5'. SW 108.7'	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
Found 5/8" rod in center of Monument box 4" below surface. Corner is in centerline of road North and South road and 3' South of centerline of road to East and West. OF MICHAEL A. McCLUNG LAND SURVEYOR NO.	Was control of
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. 13037	7
Corner C-7. Osceola County Monument, which is a 3" brass cap mounted of a 1" pipe 18" in length. Power Pole N50W 107.01 feet. Old decayed stump S15W 109.45 feet. O.B.T. 4" White Pine S30E 77.2 feet. Tele. Pedestal S30W 62.05 feet. 24" W. Pine S75W 132.2 feet.	
Signed by Mathiw McChing Date 23 Gav (98 Surveyor's Michigan License No.	

Princer B Lade 217

SURVEY & REMONUMENTATION

FEB 1 6 1999

SECTION

OSCEOLA COUNTY REGISTER OF DEEDS

98 NOV 23 AH 10: 36

Maney Crawford

Act 74, Liber 1, page 218. Found 1" iron in centerline Rd. Sign Az 145d- 43.44'. Set nail & tag NW side 36" Stump Az 145d- 108.85'. Set Nail & tag SW side power pole Az 320d- 42.08'.

Act 74, Liber 2, pages 69 & 70. Found 1" iron N45W 42.10' Telephone Pole. S60E 101.5' 11" Maple. S25E 91.85' Chris "+" in North face of gas line marker.