$\mathbb{R}^{\mathbb{N}}$

SECTION

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

For corners in Osceola		Located in:	Corner Code#		
1.	Public Land Survey		T 18 N	R 10 W	F-5
			T	R	
			T	R	·
			T	R	
2.	Property Controlling in Section	g s	т	R	
		s	T	<u>R</u>	
3.	Miscellaneous Property in Sec.	s	Т	<u>R</u>	
				R	
4.	Lot No Recorded Plat				
5.	Private Claims				

I, Robert L. Wetherell, in a field survey on October 7. hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Register of Deeds Stamp & File Number A B C D E F G H 1 J K L M 2 1 3

5 6 3 12 10 11 7 8 9 4 5 13 14 17 16 15 18 6 7 24 22 23 20 21 19 8 9 25 28 27 26 29 10 30 11 35 36 33 34 32 31 12

F-5 - 1/4 Corner common to Sections 9 & 16, T18N, R10W, Osceola Co., Mi.

Description of original monument and accessories and/or subsequent restoration:

1838 J. Hodgson, G.L.O. #1 - 8" Elm S12"E 54 Links #2 - 7" Cedar N10"W 10 Links 1971 - J. Erickson, LS 16929 L.C.R.C. - Liber 01, Pg. 75

"Set standard Osceola Monument from Highway ties and One (1) bearing tree."

#3 N.E. Cor. Box Culv. Headwall N75°W 70.35' #4 - Fence Post Dug North 27.68'

#5 - 11" Elm S34°E 37.0" 1978 – D. Hooth, M.D.O.T.

L.C.R.C. - Liber 02, Pg. 91 Found 3/" Iron Rod, "Fit old witnesses" Corner in North edge of river bottom.

Added 2" x 4' Pipe #4 - Fence Post N10°E 27.49' #5 - 5" Cherry N45°E 31.60'

#7 - 6" Cherry \$25°W 46.00"

#3 - N.E. End Conc. Headwall N45°W 70.10°

1987 – J. Erickson, LS 16929 L.C.R.C. – Liber 02, Pg. 268. "Corner removed during construction of U.S. 131. Corner re-established using M.D.O.T. plan data."

Set 1" x 8' Pipe with Osceola Co. Cap 1' above water at North edge of creek.

#4 - Fence Post N10°E 27.49' #6 - 5" Cherry N45°E 31.60°

#3 - N.E. cor. headwall N75°W 70.10°

#8 - 18" Poplar N85°W 40.14' #9 - 12" Poplar N60°W 24.08" 1998 - Craig Pullen, LS 39095

13

Survey recorded Liber 648, Pg. 321 Found Osceola County Monument 7 feet West of Creek.

#4 - Fence Post N6°E 25.66'

#10 - 10" Cherry N21°W 24.18"

#3 - N.E. Cor. Conc. retaining wall N83°W 68.15'

#11 - S.E. Cor. Conc. retaining wall. S53°W 116.20'

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found a 1" pipe (A) next to a 2" x 4' Pipe (B) (leaning) on the North edge of small creek. I also found a 1" x 24" pipe (C) with Osceola County Cap Northwesterly 3.1 feet more or less from the 1" Pipe (A). Apparently this 1" x 24" Pipe (C) had broken off (at a coupler) from the 1" Pipe (A) found on the edge of creek and someone stuck it in the ground on top of the bank. It was only in the ground approximately 8". Surveyor Pullen used the Osceola Capped Iron as found on top of the bank. I removed this Capped Pipe (C) and also the 2" x 4' Pipe (B).

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Found in good condition, #4 Found down, #5 Found dead, #6 Found dead.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the 1" x 24" Pipe with the Osceola County Cap over the 1" Pipe on the edge of Creek, and is accepted as a careful and faithful reestablishment of the position of the original corner.

N.E. corner Concrete Headwall N78°W 69 86' 1920

S.E. corner Concrete Headwall S59°W 116.33' (#11)

11" Cherry S39°W 69.92' (60d spike in E. side)

14" Poplar N18°W 28.90' (60d spike in N.E. side)

Osceola County

10-21-99 Zw.

0000 Date No V- 9, 1999

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, IAN.28, 1971

REVISED MAY 14, 1975

REVISED JAN. 1983

ADAPTED FOR WORD PROCESSING JANUARY, 1999

NO.

24624

Signed by Robert Surveyor's Michigan License No. 24624 Witness