PF

## AND CORNER RECORDATION CERTIFICATE

SECTION

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

For corners in Osceola		Loc	ated in:	Corner Code#					<u>~</u>		·		
1. Public Lánd Survey		Т	19 N	R 10 W	F-11			Ş	lancy Crawfor	ים טבני	ה ה	OSC!	
			T	R					J.	1	J i		
			T	R					2	ے د	D :	R'> 즮O	
			т	 R					OĞ	=			
2.	Property Controlling	s T	<u> </u>	_ <del>``</del>					Ti.		3	FIX.	
	in Section	-							\ '	• •	•		
		S T		_R		Registe	r of D	)eeds	Starr	ıp&F	ile Nu	ımber	
	Miscellaneous	s T		R									
	Property in Sec.			R				٠					
4.	Lot NoReco	rded Plat	·				А В	C D	E F C	3 H	IJ	KLM	
<b>5</b> .	Private Claims				1 2	6	5	4	3	2	1		
I, Robert L. Wetherell, in a field survey on November 18, 1999, do						3 4					-		
hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Of a Court of Law; established, re-established, monumented, re-monumented,							7	8	9	10	11	12	
							18	17	16	15	14	13	
							19	20	21	22	23	24	
							30	29	28	27	26	25	
recovered, found as expressed below:						11 12	31	32	33	34	35	36	
						13							
F-11 - 1/4 Corner common to Sections 28 & 33, T19N, R10W, Osceola Co., Mi.													
A. Description of original monument and accessories and/or subsequent restoration:													
1838 - S. Sibley, G.L.O. 1902 - Twp. Book							1993 – D. Erickson, LS 29245 L.C.R.C. – Liber 03, Pg. 57.						
#1 – 10" Beech N26°W 10 Links #2 – 10" Beech S26°E 18 Links				#3 – Maple N.E. 45.7°			#6 - 24" Maple N35°E 33.46'						
	#2 - 10" Beech \$26°E 18 Links  1891-1904 - Temple/Trumbull/June			#4 Maple N.W. 23.9'			#4 – 30" Maple N21°W 23.95'						
				#5 Fence Post South 30.1'			#5 - Corner Fence Post S3°W 30.45'						
	The Township of Leroy		Distance West – 2614.92'			#7 – Fence Post S67°W 65.53'							
	Was remonumented with												
1978 - D. Hooth (M.S.H.D.) 1995 - R.L. Wetherell, L.S.2													
"Found 1/2" Rod in 2 1/2" Tile"						Survey recorded Liber 589, Pg. 292							

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

#6 - 20" Maple N35°E 33.42" #3 - 27" Maple N55°E 45.30'

#4 - 27" Maple N20°W 24.80'

I found 1/2" rod inside a 3" clay tile. Corner is in the center of an East-West road and in line with old fence to South. I measured 2615.27 feet West to Section corner which checks well with the 1902 Township Book.

#5 - Corner Fence Post South 30.38'

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Found in good condition (36"), #4 Found dead, #5 Found Post (but is New), #6 Found in good condition, #7 Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the 1/2" rod with a 1-1/2" pipe with an Osceola County Remon Cap, and is accepted as a careful and faithful reestablishment of the position of the original corner.

36" Maple N60°E 46.41' (60d spike in S.E. side) #3 24" Maple N36°E 33.43' (M.S.H.D. Nail & Tag in E. side) #6 16" R. Pine S13°E 57.48' (60d spike in E. side) #8 7" Spruce S14°W 36.72' (60d spike in W. side)

Surveyor's Michigan License No. 24624

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS MAN 28 A STATE BOARD OF LAND SURVEYUNGBOAN 28; 1971 REVISED MAY 14, 1975 REVISED JAN. 1983 ADAPTED FOR WORD PROCESSING JAMUARY, 1999

#8 -16" R. Pine S13°E 57.47"

#4 - 30" Maple N25°W 23.93'

#5 - Corner Fence Post South 30.45' #6 - 20" Maple N34°E 33.41'

Osceola County

APPROVED LAND CORNER P.A. 345 OF 1990

> LIBER B PAGE 572

36 316 16 ROBERT L WETHERELL LAND JAVEYOR NO. 24624 W ( 4 4 9 9 3