

JAN 1 7 1996 LAND CORNER RECORDATION CERTIFICATE COMMISSIGNED Requirement of Act 74 Mich. P.A. 1970.

For corners in	COMMISSION Was Redniced	ement of Act 74, Mich. P.A.	1970
Osceola	Located In:	Corner Code ##	
(County)	···		APPROVED LAND CORNER
1. Public Land Survey	T 20N R 10W	<u>I-6</u>	P.A. 345 OF 1990
	T R		Osceola County
	T R		1995
2. Property Controlling	T R S T R		Malker My Dung
in Section	S T R		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
A Lot No	, Recorded Plat		
	, riecorded / lat		A B C D E F G H I J K L
			2 - 6 - 5 - 4 - 3 - 2 - 1 -
			3
. Daniel E Cabrin	Norro	mhor Q5	4 - 7 - 4 8 - 4 9 - 10 - 11 - 12 -
	DS부MA a field survey on <u>Nove</u> requirements of P.A. 74, Michigan P.A.		- 5 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
in lines 1 and 2 above were	e in conformance with regulations an	d rules therefore as required in t	he 18-17-16-15-0-14-13-
	structions of the United States Depart of a Court of Law and/or that the corne		15
above were in conformance	with the rules of the Michigan Board of	f Land Surveyors or by a Decree o	fa
Court of Law; established expressed below:	i, re-established, monumented, re-r	nonumented, recovered, found	as 10 30 29 28 27 26 25
	corners, all in the same town ar	d range, may be recorded	11
on this certifical		id fallige, filely be footing	12 31 32 33 34 35 36
			13
	al monument and accessories and nal corner was a wood po		the
South	iai corner was a wood po	ac acc 40 chairm iron	· che
	S20W 15 lks., Hemlock	7 N14E 40 lks.	
page 4, mi	y Surveyor Records, Burd id page - "Sept. 21, 191 1/2W 33 ft., Post N46 1/ d on back)	8, 1/4 corner 14 & 15	, 2" pipe,
I-6) Found 1/2'	revidence found and/or method a 'iron over 2" pipe in c nd 1 foot South of road	enterline of N-S road	
,			
		,	
			•
•			
	• .		
C. Description of monur	ment for corner and accessories e	established to perpetuate loca	ting the position of the corner:
	ounty Monument, which is		
l" pipe 30)" in length.		
	1/2" iron over found 2" S 1' S of road to East.	pipe in centerline of	
583°W 46	.46 Twin Maple		
N16°W 68.	.98 P.Pole		
547°E 83. N11°E 160.	.75 ll" Elm .81 8" Balsam		
SI SUCA			
Marie Land Company		10	7-12-95
Signed by DONEL E	A Jufan	Date	10-13
Surveyor's Michigan Lice	nse No 24617	- FE	IRM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197
SURVEYOR			REVISED MAY 14, 197 REVISED JAN., 198

95 DEC 14 PM 3: 27

Maney Caregord

County Surveyor Records, Burdell Twp. Book, Page 84, June 21, 1950 - shows breakdown of North 1/2 of Sec. 15, a measurement of 1196 ft. is shown from the East 1/4 corner to the Northeast corner of Sec. 15, E. 1/4 corner shown with witnesses 2" pipe - f.p. East 33.75 ft., f.p. SW 36.5 ft.

Michigan State Highway Department Gov't witness record by M. A. Koivisto dated November 1962 & also shown on MDOT Fed. Proj. #F133(21), State Proj. #67015, Route US-131, sheet #13,
 West 1/4 corner, found. 2" pipe, West 33.42 ft. fence post, N22W 67.62 ft. power pole

S45E 50.10 ft. tel. pole

Gary R. Stonerock - LCRC dated 6/19/73, recorded Liber 1, page 191. While performing a survey in Section 15 a E. 1/4 corner was set. As stated in the LCRC - "Found NE and SE corner of Section 15 and measured the mile, distance found to be 5274.60 ft., the halfway point fell 348.75 ft. South of an iron at the intersection of Diamond Road and a gravel road which intersects from the East. This iron and the NE Section corner were held for line and the E 1/4 corner was set halfway. A deflection is at the East 1/4".

Also reviewed Wade - Trim / Granger Certificate of Survey dated Nov. 11, 1988, Recorded in liber 505, page 489

Wade - Trim / Granger Certificate of Survey dated May 8, 1989, Recorded in liber 514, page 625

J.L. Wilcox & Associates, Inc. Certificate of Survey dated Sept. 27, 1989, Recorded in liber 527, page 682

Jack F. Erickson Certificate of Survey dated Sept. 24, 1992, Recorded in liber 556, page 469

Missaukee Surveying & Engineering, Inc. 1994 survey for the NE.1/4 of the SE 1/4, which was submitted to the peer group for consideration of the East 1/4 of Section 15. The corner submitted for consideration was the 2" pipe below a 1/2" pipe at the intersection of Diamond Road and a gravel road to the East and Northerly 348.75 ft. of the Stonerock corner. Occupation in the SE 1/4 and a pipe found at the S. 1/8 corner on the N. & S. 1/4 line of Sec. 15, appeared to be in agreement with found 2" pipe.

After reviewing the evidence listed above, the Peer Group approved the location monumented with the 2" pipe which is located Northerly 348.75 ft. of the Stonerock corner although the Stonerock corner was in closer agreement with GLO distance calls for the Sec. line and also with calls to a creek and swamp edge. This position is the first known record after GLO Survey (established in 1918) and felt to be the best position and causing less conflict, with 80 years of history and occupation.

The Peer Group felt the role of the Land Surveyor is not to upset or disturb occupation and land boundaries unnecessarily causing conflicts and lawsuits.