SURVEY & REMONUMENTATION

SEP 1 5 1994

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

I. Matthew McClung a field survey on	& File Number G H J K L 3 2 10 11 12 15 14 13 22 23 24 27 26 25 Aug. Aug. Aug.
1. Public Land Survey T	& File Number G H J K L 3 2 10 11 12 22 23 24 27 26 25 34 35 36 Aug. Aug.
2. Property Controlling S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Prop	G H J K L 1 3 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2. Property Controlling S T R R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R R R Register of Deeds Stamp Property in Sec. S T R R R R R R R R R R R R R R R R R R	G H J K L 1 3 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2. Property Controlling S T R R 3. Miscellaneous S T R R 4. Lot No. Recorded Plat S Private Claims Register of Deeds Stamp Property in Sec. S T R R 4. Lot No. Recorded Plat S Private Claims Register of Deeds Stamp Property in Sec. S T R R 4. Lot No. Recorded Plat S Private Claims Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R R Register of Deeds Stamp Property in Sec. S T R R R R R Register of Deeds Stamp Property in Sec. Stamp Property in Sec. S T R R R R R R R R R R R R R R R R R R	G H J K L 1 3 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2. Property Controlling in Section S T R R Register of Deeds Stamp Property in Section S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R R Register of Deeds Stamp Property in Sec. S T R R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R R Register of Deeds Stamp Property in Sec. S T R R R R Register of Deeds Stamp Property in Sec. S T R R R R Register of Deeds Stamp Property in Sec. S T R R R R Register of Deeds Stamp Property in Sec. S T R R R R Register of Deeds Stamp Property in Sec. S T R R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp P	G H J K L 1 3 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
in Section S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R Register of Deeds Stamp Property in Sec. S T R R R R Register of Deeds Stamp Property in Sec. S T R R R R R R R R R R R R R R R R R R	G H J K L 1 3 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
3. Miscellaneous S T R R Register of Deeds Stamp Property in Sec. S T R R Recorded Plat 4. Lot No. Recorded Plat 5. Private Claims 1. Matthew McClung a field survey on June 19 19494	G H J K L 1 3 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
4. Lot No	G H J K L 1 3 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
4. Lot No, Recorded Plat	22 23 24 25 25 26 25 26 25 26 26 26 26 26 26 26 26 26 26 26 26 26
Matthew McClung a field survey on	22 23 24 25 25 26 25 26 25 26 26 26 26 26 26 26 26 26 26 26 26 26
Matthew McClung a field survey on	22 23 24 25 25 26 25 26 25 26 26 26 26 26 26 26 26 26 26 26 26 26
Matthew McClung a field survey on June 19	22 23 24 25 25 26 25 26 25 26 26 26 26 26 26 26 26 26 26 26 26 26
I. Matthew McClung a field survey on June 19 19 1994 do hereby certify that under requirements of PA. 74. Michigan PA. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with the regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3.4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman on 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonumentate program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing comer: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	22 23 24 25 25 26 25 26 25 26 26 26 26 26 26 26 26 26 26 26 26 26
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman on 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonument program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	22 23 24 25 25 26 25 26 25 26 26 26 26 26 26 26 26 26 26 26 26 26
do hereby certify that under requirements of PA. 74, Michigan PA. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman on 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonumented program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of comer evidence found and/or method applied in restoring or reestablishing comer: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surfact high steel fence post, by State, marking conservation easements of the conservation and the conservation easements of the conservation and the conservation easements of the conservation and the conservation easements of the conservation ea	22 23 24 25 25 26 25 26 25 26 26 26 26 26 26 26 26 26 26 26 26 26
do hereby certify that under requirements of PA. 74, Michigan PA. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman on 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonumented program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of comer evidence found and/or method applied in restoring or reestablishing comer: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surfact high steel fence post, by State, marking conservation easements of the conservation and the conservation easements of the conservation and the conservation easements of the conservation and the conservation easements of the conservation ea	Aug. Aug. Aug. Aug.
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Bureau of Land Management or by a decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman on 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonumental program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement in the constant of the constant of the conservation easement is 10" above surface of the conservation easement is 10" abov	Aug. Aug. Aug. Aug.
A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman or 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonument program, in which surveyors Temple and Trumbull, did the work. From 1891 to 1904 approximately, Osceola County had a remonument set each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	Aug. Aug. Aug. Aug.
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman on 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N2IE 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonuments program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	Aug. Aug. Aug. Aug.
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman on 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonuments program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of comer evidence found and/or method applied in restoring or reestablishing comer: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	Aug. Aug. Aug. Aug.
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman on 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonuments program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	Aug. Aug. Aug. Aug. Aug. Aug. Aug. Aug.
on this certificate. A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman on 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonuments program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easements.	tion r the e placed d to be 3
A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman or 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonuments program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	tion r the e placed d to be 3
A. Description of original monument and accessories and/or subsequent restoration: The original corner was set by deputy surveyor Francis Coleman or 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonuments program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	tion r the e placed d to be 3
The original corner was set by deputy surveyor Francis Coleman on 1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonuments program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	tion r the e placed d to be 3
1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonuments program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	tion r the e placed d to be 3
1, 1856. Set wood post 105.70 chains from the North. Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonuments program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	tion r the e placed d to be 3
Hemlock 16" N21E 12 lks. Hemlock 16" S60W 6 lks. From 1891 to 1904 approximately, Osceola County had a remonuments program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	e placed d to be 3
From 1891 to 1904 approximately, Osceola County had a remonumental program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	e placed d to be 3
From 1891 to 1904 approximately, Osceola County had a remonumental program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	e placed d to be 3
program, in which surveyors Temple and Trumbull, did the work. For most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	e placed d to be 3
most part, a 3" glazed tile filled with cinders from a forge, were at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	e placed d to be 3
at each government set corner in the township. There were suppose tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	d to be 3
tile per corner, placed atop of each other, (continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	
Found 5/8" rod and Cap No. 13037 inside tile. Removed rod & cap, Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	
Osceola County Monument inside tile. Monument is 10" above surface high steel fence post, by State, marking conservation easement.	
high steel fence post , by State, marking conservation easement.	and grove
ART ATE OF	e. o
ARRIVAN, E. O.	THE PERSON NAMED IN
ART KA towards	MICH
	C. C.
MA MA	I I TEVY
E_ [A. Mi	CLUNG \ 🐧
	AND TE
SUF	VEYOR DE
	NO. $/23$
	037 Leve No Hi
	SUPPLIE
	ANI
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner E-3. Osceola County Monument, which is a 3" brass cap mount pipe 30" in length. Steel fence post N83E 102.50 feet. 10" Maple West 11.8 feet.	lef.""
Compon F.3 Ogogola County Monument, which is a 3" brass cap mou	ited on a
Corner E-5. Objecta County Hollametro, which is a so stars our mean	
Stool force post NRSE 102 50 feet.	
10" Manla Wast 11 8 feet	
8" Maple South 23.50 feet.	
6" Maple N55E 24.25 feet.	
O HUDTE MODE 51.50 1000.	
·	
A	
$\int_{M_{1}} \int_{M_{2}} \int_{M$	
Signed by Mathew M / lung Date	
Supervise Michigan License No. 13037	
Surveyor's Michigan License No. Porm Approved by Michigan State BOARD	F 1 4 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
LIBER A PAGE 145	F LAND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 19

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County records.

This corner has one LCRC recorded by McClung.

DISCEPT OF DEEDS

94 AUG 12 PH 3: 04

7 Aug Caushid