Surveyor's Michigan License No. 31600

## LAND CORNER RECORDATION CERTIFICATE

|   | g Requirement of Act 74, Mich. P.A. 1970   |  |
|---|--|--|
| For corners in Oscoda Located In:   | Corner Code #  | Liber 4 pg. 6  |
| 1. Public Land Survey T 26N   | R 2E 6 - 6   | STATE OF MICHIGAN<br>OSCODA COUNTY<br>FILED  |
| т   | R R  | 2 AUG 95 9:35 A.H.   |
| 2. Property Controlling S T<br>in Section S T<br>3. Miscellaneous S T   | R R R  | PATSY J. PETERS REGISTER OF DEEDS ister of Deeds Stamp & File Number   |
| Property in Section S T   | K  |  |
| 4. Lot No, Recorded Plat  |  | A B C D E F G H I J K L  |
| 5. Private Claims   |  | 2 6 5 - 3 - 2 - 1 - 1  |
|   |  | 3  |
|   |  | 4 7 - 8 - 9 - 10 - 11 - 12 -   |
| I, Marvin E, Myers , in a field survey on do hereby certify that under requirements of P.A. 74, hin lines 1 and 2 above were in conformance with regular manual of survey instructions of the United State Management or by a decree of a Court of Law and/or 5 above were in conformance with the rules of the Noerree of a Court of Law; established, re-established as expressed below:  NOTE: Not more than 4 corners, all in the same on this certificate. | Michigan P.A. of 1970, the comer points mentioned ations and rules therefore as required in the current as Department of the Interior, Bureau of Land that the corner points mentioned in lines 3, 4 and Michigan Board of Professional Surveyors or by a monumented, re-monumented, recovered, found  | 5<br>6 18 17 15 15 14 13 - 13 - 13 - 14 13 - 13 - 14 13 - 15 15 15 15 16 15 15 16 15 15 16 15 15 16 15 16 15 16 15 16 16 16 16 16 16 16 16 16 16 16 16 16  |
| A. Description of original monument and acco  | essories and/or subsequent restoration:  |  |
| GLO-L. Clawson 1839 Mon-Post WIT: 8" Aspen S62°W 44 1ks. 7" Aspen N85°W 24 1ks. Randall Feb. 1893 Mon-Unknown WIT: None given C.O. Seeley Sept. 21, 1914 Mon-Set Post WIT: NBT 12" Soft Maple S66°E 0.39 1ks. NBT 10" Water Elm S21°W 1.08 3/4 1ks.   | GLO-G. Veal Oct. 1935 Mon-Set Conc. Mon. with Brass Tablet by proportate distance WIT: 4" Birch S56°E 19 lks. 4" Elm N83½°W 62½ lks. Fence N. 12 lks. & E. 2 lks.  G. Henning 1953 Mon-Fd. US GLO Mon. WIT: NBT Spike 10" J.Pine N40½°E 47.00' NBT Spike 7" J.Pine S21°W 51.20' G. Henning Aug. 1956 Mon-Broken off WIT: US 6" Birch S56°E 12.50' BT 16" Maple S29°W 52.50' BT 8" Maple N47°E 44.80' | L.2, pg.170 N. Caldwell July 28, 1 Mon-Unknown WIT: ½" Bar & Cap N88 3/4"E 33.00' LCRC L.3, pg.90 L.4, pg.489 N. Caldwell July 16, 1 Mon-Fd. 6" Dia. Conc. Mon. replace with USFS 5"x5"x36" Conc. Mon. WIT: ½" Rerod N87°W 33.00' ½" Rerod & Cap #12018 N89°E 33.20' Power Pole N24°W 69.25' 8" Maple S35°E 25.85' |
| B. Description of corner evidence found   | and/or method applied in restoring or ree  | stablishing corner:  |
| Found USFS 5"x5" Concrete Monument Accepte  | d as a careful and faithful establishment  | of the position of the corner.   |
|   | Cour<br>Pe   | PPROVED  Ity Remonumentation  Per Review Group  CC/3/#0695   |
| Mon-USFS 5'x5" Conc. Mon. WIT: ½" Rerod N87°W 33.00' ½" Rerod & Cap #12018 N89°E 33.20' Power Pole N24°W 69.25' 8" Maple S35°E 25.85'   | ccessories established to perpetuate locating the  | e position of the comer:   |
| The said to the   |  |  |

URVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983