

DEC 01 1998

## SECTION

Located In:

For corners in

**OTTAWA** 

## OTTAWA COUNTY REMONUMENTATION

Corner Code #

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

98 SEP 29 PM 1: 56

1. Public Land Survey Told T	N   R   16W   L-3 (N 1/4 Cor Sec   12) Port Sheldon   Township	REGISTER OF DEEDS OF TAMA CUIDAY, MI
2. Property Controlling S T in Section S T	R R	
3. Miscellaneous ST_	R	<b></b>
Property in Sec. S T_	R	Register of Deeds Stamp & File Number
	<u> </u>	register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims		A B C D E F G H I J K 1
	·	2 6 5 4 3 2
		3
Randal J. Vugteveen in a field surv	ey on, 19 do hereby state that under	
	e corner points mentioned in lines 1 and 2 above were in	4   1   1   1   1   1
	required in the current manual of survey instructions of the	5
	Land Management or by a decree of a Court of Law and /or above were in conformance with the rules of the Michigan	6 -18 -17 -16 -15 -14 -11
Board of Land Surveyors or by a Decree of a C	Court of Law; established, re-established, monumented,	7
recovered, found as expressed below:		8 19 20 21 22 23 2
NOTE: Not more than 2 corners, all in the san	ne town and range, may be recorded	9
on this certificate.		10 30 29 28 27 26 2
		11
્રું <sup>હત</sup>		12 31 32 33 34 35 3
A. Description of original monument and acc L-3 GLO May 1832	essories and/or subsequent restoration:	13
Calvin Britian	Liber 1 Page 641 (J. Clapp 1972)	MSHD 1950± (Project 70-41, sheet #5)
Set Post	Found RR spike in Left Lane South Bound U.S31	1/8th Cor East 1323.50'
18" Beech N57°W 28 Links	Tel. Pole SW 51.05	Centerline N Bound US 31 East 129.3'
7" White ASH 577°E 25 Links	Tel. Pole SW 42.08'	MSHD angle between North line, Northeast 1/4,
	St. Sign NE 62.14'	Section 12 and centerline alignment of US-31 to
		North = 115*08*
i sub		
B. Description of corner evidence found and	or method applied in restoring or reestablishing con	ner:
Found RR Spike in Left Lane South Bound US-31	•	
fron in Monument Box at 1/8th cor N90°E 1322.93°	Accepted RR Spike as a careful and faithful	1
Centerline North Bound US-31 N90*E 130.94*	perpetuation of the position of the original corner.	
Measured angle between North line, Northeast 1/4,	Replaced RR spike with standard Ottawa County cap	
Section 12 and centerline alignment of US-31 to	on 3/4" X 24" iron bar.	
North = 115*07'08"		
ફુ <i>ન</i>		7/20198
	·	1/20/1
•	,	1901
C. Description of monument for corner and ac	cessories established to perpetuate locating the pos	sition of the corner:
Set 3/4" X 24" Iron Bar with Ottawa County Remon C	ap	g of the state of
		and the second second
Set Nail and Remon Tag in W Side 8" Pine AZ = 25"	87.01'	
Set Nail and Remon Tag in S side 8" Pine AZ = 44" 77.82'		<b>8</b> 5
Set Nail and Remon Tag in East side Power Pole AZ	= 315° 117.05'	The very way in the Bo
Southeast corner of a 4" X 6" Wood sign post AZ = 2		
Southest corner of a 4" X 6" Concrete Post AZ = 20	4* 122.43'	
Centerline of Taylor Street AZ 0° 1.5'	7.01	\$9.00 CORNER Receirt #13502
Centerline of South Bound, US-31 pavement AZ 245°	1.0/	Transport of the state of the s
S 21/1 / //-	./	177 NO O
Signed by / M. J	Date <u></u>	CY C 2/77 O
Surveyor's Michigan License No.	28429	