RECORDED

FEB 24 2000

OTTAWA COUNTYREMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

99 DEC -2 PM 1:13

SECTION	San Siller
For corners in OTTAWA (County) Located In: ROBINSON (Township) Corner Code #A-3	REGISTER OF DEEDS OTTAWNS THE MI
1. Public Land Survey T 7N R15W S.W. Cor. Sec. 6 T R T R T R	
2. Property Controlling S T R COMMON CORNER in Section S T R 3. Miscellaneous S T R	Register of Deeds Stamp & File
Property in Sec. S T R	Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L
5. Private Claims	2 6 5 4 5
11/15/99	3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
I, Robert E. Lemke, surveyor, in a field survey on September 7, 1999 do hereby state that under	5
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current	6 10 17 15 15 12
manual of survey instructions of the United States Department of the Interior, Bureau of Land	7
Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land	8 20 21 22 23 24
Surveyors or by a Decree of a Court of Law; established, reestablished, monumented,	10-30-29-28-27-26-25
recovered, found as expressed below:	1
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	1 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	Robert E. C.
SEE BACK OF SHEET FOR CORNER HISTORY	Lemke
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	SURVEYOR No. 40160 Land Survey
FOUND CAST IRON MONUMENT IN MONUMENT BOX 9" BELOW THE TOP OF THE MONUMENT BOX.	den Land Sur
FOUND NAIL ON EAST SIDE OF 32" OAK 6" ABOVE GROUND. FOUND NAIL ON N.E. SIDE OF ABOVE 32" OAK 12" ABOVE GROUND.	N.W. 39.90° N.W. 41.11°
MEASURED TO SIGNAL ON N.W.'LY SIDE OF 20" OAK 12" ABOVE GROUND (DID NOT FIND ANY OTHER WITNESSES	OT FIND WITNESS) S.E. 69.5'

THIS CORNER(A-3) WAS DETERMINED TO BE COMMON WITH M-3, SECOR. SECTION 1, GRAND HAVEN TOWNSHIP IN REMON LIBER 2, PAGE 69 BY TOM JOINER IN DECEMBER OF 1994. M-3 WAS PEER APPROVED ON DECEMBER 12, 1994. ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER

■C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
■A-3 CAST IRON MONUMENT IN MONUMENT BOX 9" BELOW THE TOP OF THE MONUMENT BOX.

Fd. NAIL WITH OTTAWA COUNTY REMON. TAG ON N.E.'LY SIDE OF 32" OAK 1' ABOVE GROUND N.45°W. 41.11' SET NAIL WITH OTTAWA COUNTY REMON. TAG ON S'LY SIDE OF 36" OAK 1.5' ABOVE GROUND N.75°E. 123,111 Fd. NAIL WITH OTTAWA COUNTY REMON. TAG ON W'LY SIDE OF 20" OAK 0.6' ABOVE GROUND S.30°E. 70.36' SET NAIL WITH OTTAWA COUNTY REMON. TAG ON E'LY SIDE OF 13" OAK

0.2' ABOVE GROUND

CENTERLINE OF 144TH AVENUE 0.5' WEST AND CORNER IS ON CENTERLINE OF JOHNSON STREET. 0.2' ABOVE GROUND S.45°W. 90.96'

TENTERLINE OF 144 AVENUE 0.5 WEST AND CORNER IS ON CENTERLINE OF JOHNSON STREETS TO B3(T7N, R15W) IS 2739.11' PER SDI MEASURE

*\frac{1}{2}-A3(T7N, R15W) PER SDI MEASURE IS 2647.42'.

DCCUPATION LINE (CONSISTING OF TREE LINE AND CHAIN LINK FENCE) IS 1324'+/- NORTH OF A-3

Signed by Robert E Lembe

te <u>//-/5-/999</u>

For SDI CONSULTANTS, LTD

Burveyor's Michigan License No. 40160

SEE BACK

Receipt #64945

SECTION

OTTAWA COUNTY ROBINSON TOWNSHIP TOWN 7 NORTH, RANGE 15 WEST

A-3

A. Description of original monument and accessories and/or subsequent restoration

```
-G.L.O.
    WEST BETWEEN SEC'S 6 & 7
    81.45 WEST BOUNDARY AT POST & SET COR
    TO SEC'S 6 & 7
    MAY 20, 1832 (CALVIN BRITAIN)
   20" PINE S. 59° W. 25 LINKS
   20" PINE N. 65° W 6 LINKS
-OTTAWA COUNTY ROAD COMMISSION NOTES
    SET 1/2" GAS PIPE 12-10-57 (NO INITIALS)
    14" B. OAK N.W. 40.3"
    12" W. OAK N.E. 49.2"
    12" B. OAK N. 20° E. 60.8'
    12" R. OAK S.W. 118.4"
    N. 56° W. 39.4' IRON
    N. 43° 30' E. 48' IRON
-THOMAS JOINER, L.C.R.C. RECORDED LIBER 3 PAGE 380, RECORDED JULY 27, 1979
   FD. 1" IRON
   SET CAST IRON MONUMENT
       30" OAK
                       NW
                               39.90
       48" OAK
                       NE
                               59.70
       18" OAK
                       SE
                               69.60*
       TELE. POLE
                       SE
                               46.50'
    JOINER SHOWS SAME WITNESSES ON RECORDED BOUNDARY SURVEY:
       LIBER 8 PAGE 888 RECORDED: 10-11-88
       LIBER 8 PAGE 889 RECORDED: 10-11-88
-JOHN CLAPP, HOLLAND ENGINEERING, RECORDED BOUNDARY SURVEY, LIBER 8 PAGE 615, 5-19-95
   1" IRON
      30" OAK
                       NW
                               39.90'
       48" OAK
                       NE
                               59.70
      18" OAK
                       SE
                               69.60'
      TP
                       SE
                               46.50
      ST. SIGN
                       NW
                              24.65
      A-4 NORTH TO A-3 = N00^{\circ}10'30"W 2650.24
-GERALD FORD, HOLLAND ENGINEERING, RECORDED BOUNDARY SURVEY, LIBER 8 PAGE 907, 3-20-97
  (FORD SHOWS SAME WITNESSES ON RECORDED BOUNDARY SURVEY, LIBER 9 PAGE 43, 12-8-97)
  CAST IRON MONUMENT
      30" OAK
                      NW
                              39.90
      48" OAK
                      NE
                              59.70
```

-FIELD NOTES FOR JOINER BOUNDARY SURVEY A-3 NORTH TO A-2 = N02°19'35"E 2647.76'

SE

SE

A-3 EAST TO B-3 = N89°44°00"E 2739.12

69.60'

46.50*

18" OAK

TP