SURVEY & REMONUMENTATION

APR 2 4 1995

5. Private Claims ___

expressed below:

John Mullett, Deputy Surveyor

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

RECORDED

95 DEC 15 AMII: 47

For comers COMMISSION	Filing Requirement of Act 74, Mich. P.A. 1970		Chylin Bullman
Ottawa (County)	Located In:	Corner Code ##	REGISTER OF DEEDS OTTAWA COUNTY.MI
	***	6.00	

1. Public Land Survey т<u>8N</u> в <u>14W</u> I-8 (W¼, 23) T ____ R ___ Polkton Twp. T _____ R __ S ____ T ___ R ___ 2. Property Controlling S ___ T ___ R ___ S ___ T ___ R ___ S ___ T ___ R ___ in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec.

December 1, i, <u>Donald W. Schiele</u>, in a field survey on <u>December 1</u>, 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

___ , Recorded Plat __

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: I-8 % corner common to Sections 22 & 23, Polkton Twp. Original Government L.C.R.C. recorded in Liber 3, Corner Record:

Page 245 12-29-77 L.C.R.C. recorded in Liber: Page 46, 4-9-80 Page 245, 12-29-77

Corner Record: Set or section post Angle Iron between Sec. 22 & 23 N55°W 69.04 Spike in P. Pole N75°E 65.001 Post Center of Man Hole Elm 11 S39E 11 B Ash 11 S29W 19 S 2°E

30.151 Spike in P. Pole

N40°W 48.18' Center of Fire Hydrant

"L" Iron C/L P & T pole N60°W 69.481 C/L top hyd N45°W 48.10' C/L St. sign post N75°E 95.40'

April 9, 1837 SE cor conc. blk. bldg. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: N85°W 159.751

I-8 Found 24"-long Angle Iron, 3" below surface, and accepted as a careful and faithful perpetuation of

the position of the original corner.

N71°E 64.97 Centerline Manhole Cover SE corner, Concrete Block Building Found nail in East side of Power Pole Found nail in SW side of Power Pole N83°30'W 159.71' N59°W 69.04 N59°W 69.47 On centerline asphalt roads North, South & East

On C/L road North & East

OF MICH

P.A. 345 OTTAWA COUNTY

PEER APPROVED 12/12

Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Removed 24"-long Angle Iron and replaced with 3/4" X 24" Steel Bar with Ottawa County

Remon Cap 24" below surface in Manument Rev

Remon Cap, 24" below surface in Monument Box. Set Ottawa County Remon Tag & nail in SE side of 14" Poplar Set Ottawa County Remon Tag & nail in SW side of 10" Twin Ash N64°E 108.07 S49°30'E 81.18' S42°W 42.66' Centerline Fire Hydrant SE corner, Concrete Block Building 159.711 N83°30'W Set Ottawa County Remon Tag & nail in SW side of Power Pole On centerline asphalt roads North, South & East 69.421 N59°W

el W. Schile DEC./2,/994

Surveyor's Michigan License No. .

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAH., 1983