## SURVEY & REMONUMENTATION

APR 2 5 1995

## OTTAWA COUNTY REMONUMENTATION

## RECORDED

LAND CORNER RECORDATION CERTIFICATE

94 DEC -8 PM 12: 34

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

REGISTER OF DEEDS OTTAWA COUNTY MI

Uttawa	Located In:	Corner Code ##	ÖŤĨ	AWA COUNTY, MI
(County)				
. Public Land Survey	т <u>8N в 14W</u> .	J-7 (N¼, 23)		
. I done carle dervey	T R	Polkton Twp.		
	T R			,
	T R			
. Property Controlling	S T R			
in Section	S T R			
. Miscellaneous	S T R		Danistas at Danis	
Property in Sec.	S T R		Register of Deed	s Stamp & File Number
	•			
. Lot No, Re	ecorded Plat		A B C	DEFGHIJKL
. Private Claims				
•			2 - 6	⋾ <del>─</del> ┼─┆╶┼─┆╶
	`	•	3	
			4	39101112-
	in a field survey on Nove			
	uirements of P.A. 74, Michigan P.A. conformance with regulations an			7-16-15-14-13-
	ctions of the United States Depar		_ 1 1 1 1	
•	Court of Law and/or that the corne			
	n the rules of the Michigan Board o			
	e-established, monumented, re-r	monumented, recovered, foun	d as	
xpressed below:			10 -30 -2	9 28 27 26 25
	rners, all in the same town a	nd range, may be recorded		
on this certificate.			12 -31 -3	233343536-
Description of original m	nonument and accessories and	d/or subsequent restoration	. 13	<u></u>
	to Sections 14 & 23,		•	
riginal Government		ecorded in Liber 1,	L C R C reco	rded in Liber 2,
orner Record:	Page 201,		Page 349, 10-	
	n PK in cent		Set ½" iron	
orner between Sec.	14 & 23 CP Pole	N42°W 37.77'	St. sign N	2°W 21.50'
emlock 20	MBT Pole	S33°E 61.80'	SW cor. brick	
no ties taken)		ch N28°E 76.25'	N3	0°E 76.2'
ohn Mullett, Deputy	Surveyor NE Cor Hse	Fnd S48°W 82.18'	NE cor. house	
pril 9, 1837		SEE REVERSE)	S4	0°W 82.0'
	·	•		
3. Description of corner ev	idence found and/or method a s at edge of Storm Ma	applied in restoring or reest	ablishing corner:	woon opposite mails
	cation of % corner on			
	thful perpetuation of			
W corner, brick por		N20°30'E	76.15'	
Senterline Fire Hydr		S65°E		OF MICHAEL
	in NE side of Telepho		40.85'	S. A. S.
ound nail in SW sid		S22°E	62.35'	* Donald W.
E corner, foundation		\$36°W	53.52' 40.85' 62.35' 82.00' 37.88'	* Schiele
	NE side of Power Pole		37.881	Land Surveyor
Jan. 11. 11. 11. 11. 11. 11. 11. 11. 11. 1		•	<u> </u>	6 No. / 0 #
			7	23517 LAND LAND
	er en			1
			j.	WHINKS PARTER
•				
3. Description of monumer	nt for corner and accessories	established to perpetuate lo	cating the position of t	he corner:
J-7 Intersection of	lines between opposi	te PK nalis at edge	Of Stocial Manifold	C OUNCI
establishes % c	orner on Manhole Cove	Γ.	N20°30'E	76.15'
SW corner, brick por	cu to House # 3/5		N20°30°E S65°E	
Centerline Fire Hydr	ant	+ side of Talanhana		
Set Ottawa County Re	mon Tag & nail in Wes	r side of Terebhoue	S36°W	
NE corner, foundatio	on to House # /8/	aids of Dowen Dolo	330 W N53°W	
Set Ottawa County Re	mon Tag & nail in SW	Sine of Lower Loie	M.CGN	30.10
Centerline asphalt r	road South, 1' West	lorth	P.A. 345 OTTAWA	A COUNTY

Surveyor's Michigan License No. 23517

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

## PART A. continued:

L.C.R.C. recorded in Liber 6, Page 222, 6-19-92

J-7

Found 4 PK nails at edge of storm MH - intersected lines to establish temp. point on MH cover.

NE cor of hse fndn SW 82.01'
Fd nail & tag in NE sde P. Pole NW 37.88'
Fd PK nail in NE sde T. Pole SE 40.86'
SW cor of brick porch NNE 76.15'
C/L top of fire hyd. ESE 53.52'

L.C.R.C. recorded in Liber 6, Page 229, 8-13-92 J-7

Found 4 PK nails at edge of MH - intersected lines between nails to set temp. point in MH cover.

NE cor hse fndn. SW 82.01' Fnd nail & tag in NE sde P. Pole NW 37.88' Fnd PK nail in NE sde T. Pole SE 40.86' SW cor of brick porch NNE 76.15' C/L top of fire hydrant ESE 53.52'

-4