LAND CORNER RECORDATION CERTIFICATE

93 DEC 15 AM 9: 32

_		
ŀΩr	corners	ın

Filing Requirement of Act 74, Mich. P.A. 1970

()) Jego	ر از نیک کارک ایسان کارک	يكنيركم	s v Clober angeres	j
		REGISTE	ROF	DEEDS	

Located In: Corner Code ## DITTAWA COUNTY, MI Crockery Township 1. Public Land Survey T_8N_R 15W SE Corner T _____ R _____ Section 10 ___ R _ T _____ R ____ 2. Property Controlling _ T _ _ R . in Section S ____ R __ Miscellaneous \$ ____ T ___ R __ Register of Deeds Stamp & File Number __ R _ Property in Sec. _ T __ __ , Recorded Plat _ Private Claims Carl P. Englert Jr. August 30 _ , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 13 A. Description of original monument and accessories and/or subsequent restoration:

L.C.R.C., Liber 1, Page 581

(8-7-1972)

Fd. Mon. Box & Iron Pipe

T.P., NE 65.63'

8" Pine, NE 78.59'

St. Sign, SE 57.13' P.P., SW 45.04'

12" Maple, WNW 67.18'

L.C.R.C., Liber 5, Page 91

(12-20-1983)

FD. Bolt Spike, Set C.I.M.

P.P., SE 45.17'

P.P., NNW 80.09'

T.P., NE 65.58'

St. Sign, SE 57.05'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found broken 4" Harrison Mon. in Mon. Box and accepted as a careful and faithful perpetuation of the position of the original corner.

P.P. NWW 80.89' St Sign SE 57.05'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-5 Set O.C. Remon. Cap over broken 4" Harrison Mon. in Mon. Box

O.C. Remon. Tag & Nail in W side 15" Spruce, N 46 degrees E 69.34' O.C. Remon. Tag & Nail in NE side 26" Spruce, S 33 degrees E 80.66'

Centerline top bolt on hydrant, N 50 degrees E 50.96'

O.C. Remon. Tag & Nail in SW side P.P., N 27 degrees W 80.16'

O.C. Remon. Tag & Nail in SE side 26" Maple, S 71 degrees W 117.68'

(E.D.M.)

Surveyor's Michigan License No.

___ Date Recember

ENGLERT JR. LAND

REMON LIBER 1 PAGE 266

18987