

SURVEY & REMONUMENTATION

APR 24 1995

COMMISSION

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 15 AM 11:45

For corners in
 OTTAWA

(County)	Located In:	Corner Code #
1. Public Land Survey	T <u>8N</u> R <u>16W</u>	I-12, E $\frac{1}{2}$ Corner Section 34 Spring Lake Twp.
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Phyllis Carlsson
 REGISTER OF DEEDS
 OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, THOMAS E. JOINER in a field survey on 11-21- 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

05-26-1832	Liber 4, Pg. 301, 04-01-82	Liber 1, Pg. 667, 11-13-72
Post set by John Mullet, D.S.	Set Cast Iron Monument	Found $\frac{1}{2}$ " Pinched iron
S86°30'E 49 6" White Oak	NE 58.32 Power Pole	SE 52.71 28" Maple
N88°W 28 6" White Oak	SE 65.10 Guy Pole	SE 59.80 Power Pole
	NW 50.85 Power Pole	SW 56.09 Guy Pole
	SW 43.42 Light Support Pole	SW 43.04 Telephone Pole
		NW 46.98 Power Pole
		NE 58.34 Power Pole

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Broken off Cast Iron Monument in Monument Box and accepted as a careful and faithful perpetuation of the position of the original corner.

Liber 4, Pg. 301, 04-01-82	Liber 1, Pg. 667, 11-13-72
NE 58.32 Power Pole	SW 43.04 Telephone Pole
SE 65.10 Guy Pole	NE 58.34 Power Pole
NW 50.85 Power Pole	

P.A. 345 OTTAWA COUNTY
 PEER APPROVED 12/12/94
Richard D. Nedewold

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Broken off Cast Iron Monument in Monument Box	
Top Operating Nut on Hydrant	Az. 38° 46.08
O.C. Remon Tag & Nail in S side 31" Oak	Az. 65° 75.87
O.C. Remon Tag & Nail in NE side 7" Spruce	Az. 130° 66.10
O.C. Remon Tag & Nail in S side 12" Maple	Az. 302° 76.03



Signed by Thomas E. Joiner Date 12-9-94
 Surveyor's Michigan License No. 18435

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1975
 REVISED JAN., 1983