LAND CORNER RECORDATION CERTIFICATE Filling Requirement of Act 74 Mich D & 1970

For corners in Ontonagon	Located In:	Corner Code #	HOII. P.A. 1870						
(County)									
1. Public Land Surve	tR_ TR_ TR_								
Property Controllii in Section Miscellaneous Property in Sec.	ng S <u>I</u> T 46N R S <u>I</u> T R S <u>I</u> T R S <u>I</u> T R	39W 12		Regist	ter of De	eds Sta	ımp &	File Nu	mber
	Recorded Plat		- ,	A B	C D E	F G	н	ı j þ	C L M
O. F 114010 CIBILING	· ·	· · · · · · · · · · · · · · · · · · ·	 :	. <u>L</u>	$\perp \! \! \downarrow \perp$	_!_	_ ↓_	L	_
		Sep 23 1997	•	لل	الآلا	11	للّ	<u> </u>	•
requirements of P.A. 74, conformance with regulation United States Department that the corner points me Board of Land Surveyor recovered, found as expressions.	Michigan P.A. of 1970, the come one and rules therefore as required (of the Interior, Bureau of Land Ma ntioned in lines 3, 4 and 5 above wa a or by a Decree of a Court of seed below: (2 comers, all in the same town	, 19 do hereby sr points mentioned in linee 1 and 2 in the current manual of survey inst inagement or by a decree of a Court war in conformance with the rules of Law, established, re-established, and range, may be recorded	above were in tructions of the of Law and for if the Michigan	19—19— 0—30—	20	-16 -21 -28	-10	-23	-12 -13
A. December of extent	and manufact and accessed	e andior subsequent restoration	1: 1:		3'2	_3'3 <u></u>	3i4	3'5 	36
2-Sec. 1) South 1/16	corner of Section 1. Corne	e and/or subsequent restoration or previously recorded in 199	T by Joseph W. L	ett, RLS	\$ #21576	in Lib	ar 3 pa	ige 152	•

Ontonagon County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec.1) Recovered the 1991 monument as described in the previous record. A retracement of Section 1 and of the 1991 Lett survey revealed that the 1991 survey was erroneous in several respects. I rejected the Lett monument as representing the position of the corner. I established the corner midway and on a straight line between the Center of Section 1 and the South 1/14 corner of Section 1. The South 1/4 corner falls in the Bond Falls Flowage. It's unmonumented position was determined by proportionate measurement, according to the original record between the SW and SE corners of Section 1. At the position for the corner, I placed a 1°1.D. x 32° iron pipe capped with a yellow plastic cap which is stamped "MICH DNR PS 33986", set flush with the ground. Corner placed and witnessed by O.Lampela and 8.Wheeler. The 1991 monument was found 7.00' north of this position.

C. Description of monument for corner and accessories established to perpetus (12) Set 1 pipe with plastic cap. Blazed and scribed the following: 16 Maple N43M 30.2' "1/16S BT" 6" Sugar N73E 30.2' "1/16S BT" 5" Sugar S33E 30.4' "1/16S BT" 6" Sugar S73W 9.4' "1/16S BT" 8earings are eagnetic. Distances to notch in lower blaze. Set a squared post adjacent.	STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986
Signed by State J. Syngapoli. Surveyor's Michigan License No. 33986	

For the Michigan Department of Natural Resources - Forest Management Division