LAND CORNER RECORDATION CERTIFICATE

For corners in	rang re	equirement of Act 74, Mich. P.A.	1870					
Ontonagon (County)	Located in:	Corner Code #						
1. Public Land Survey	T <u>46H</u> R <u>39N</u> T R T R T R	K3						
2. Property Controlling in Section	S 1 T 46N R 39N	15						
3. Miscellaneous Property in Sec.	S TR S TR S TR	: <u> </u>	Regis	iter of Di	eds Sta	ımp &	FNe N	lumber
4. Lot No, Reco			1 A B	с в 1	F G	н	<u> </u>	K L
	Sec	29 1997	2 - 6-	╅╌┇╌	_i_	š	- 2-	i-
requirements of P.A. 74, Michig	, in a field survey on on P.A. of 1970, the comer poi		n .	┼-╏-	g	—¦ —10— 		-12-
United States Department of the that the corner points mentioned Board of Land Surveyors or by	Interior, Bureau of Land Manag I in lines 3, 4 and 5 above were y a Decree of a Court of Lav	he current manual of survey instructions of the ternent or by a decree of a Court of Law and /o in conformance with the rules of the Michigan w, established, re-established, monumented	F 6 18-	17	16	-15-	-14	13
recovered, found as expressed by		d	8 —1'9—	20-	-21-	_2 ² 2	23	24-
NOTE: Not more than 2 con on this certificate.	ners, as in the same lown and	o range, may be recorded	10 - 30 -	29	28	_27_ 	26-	25
A. Description of original mo	onument and accessories a	nd/or subsequent restoration;	13				Ш	<u> </u>

- (K3) Corner common to Sections 1-2-11-12. Corner reestablished in 1986 by R.L. Drahn, RLS #21564 from feature calls and measurements to adjacent corners. Recorded in Liber 2 Page 417, Ontonagon County Records.
- (15-Sec. 1) West 1/16 corner between Sections 1 and 12. Corner not established in the original survey. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (K3) Recovered and accepted the 1986 USFS monument as described in the previous record. The Maple MBT S65M is dead. The remaining 1986 witnesses are as previously recorded. Marked two new accessories as described below. This corner is being recorded in order to update the accessories. Corner remitnessed by D.Lampela and B.Wheeler, Baraga District Office.
- (15-Sec.1) Found no evidence of prior monumentation at the corner position. Established the corner midway and on a line of mean true bearing between Section corner 1333.19' West the South 1/4 corner of Section 1 1333.19' East. The South 1/4 corner falls in the Bond falls flowage. I'ts unmonumented position was determined by proportionate measurement, according to the original record between the SM and SE corners of Section 1. At the position for the corner, I placed a 1" I.D. x 32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. Corner placed and mitnessed by D.Lampela and B.Wheeler, Baraga District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the com-

notch in lower blaze.

(K3) Found 2" dia. aluminum monument with 3 1/4" dia. aluminum cap # 21564. Blazed and scribed the following: 3" Maple S81W 57.6' "SIL NBT 4" M. Birch M35E 68.6' "S1 MBT" Bearings are magnetic. Distances are to notch in lower blaze.

(15) Set 1 pipe with 4 MONR cap. Blazed and scribed the following: 13" Hemlock S75E 6.1" "1/165 BT" 7" Twin Sugar M37E 27.0" "1/16\$ 8T" "1/165 BT" 12" Hemlock W18W 33.2' 5" Maple \$67W 42.2" "1/165 BT" Placed a squared maple post adjacent. Bearings are magnetic. Distances are to

OF MIC STEPHAN J SZYSZKOSKI LAND SURVEYOR

33980 Surveyor's Michigan License No

For the Michigan Department of Natural Resources - Forest Management Division