REMONSHIP

	LAND CORNER RECORDATION CERTIFICAT Filing Requirement of Act 74, Mich. P.A. 1970		CATE	OCT 3 0 1997		
For corners in	i mig i v	equitement of Act 74, Mich. P.A. 1	1970	COMMIS	1 2 4 4 A	
ONTONAGON (County)	Located In:	Corner Code #				
Public Land Survey	T <u>48NR 39W</u> T <u>48NR 38W</u> TR	· ·	OUDITH D. RO Stonagon Cou 4/ 267		06/12/97 09:23 9.00	
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR		Register	Fase of Deeds Stam	1 01 1	
4. Lot No , Record 5. Private Claims	ed Plat			DEFG		
Corner common to S	ections 1, 6, 7 &	12, T48N R38 & 39W.	2 6-	5 4	1 J K	
i, <u>Earl W. Applekamp</u> , requirements of P.A. 74, Michigan conformance with regulations and ru United States Department of the International in that the corner points mentioned in	in a field survey on May ; P.A. of 1970, the corner point les therefore as required in the erior, Bureau of Land Managen lines 3, 4 and 5 above were in	21, 19 97_ do hereby state that under s mentioned in lines 1 and 2 above were in current manual of survey instructions of the nent or by a decree of a Court of Law and /or conformance with the rules of the Michigan established, re-established, monumented,	3 4 7 5 5 6 -18 7 8 -19	- 8 — 9 — 1 17 — 16 — 19	0 11 1	
NOTE: Not more than 2 corner on this certificate.	s, all in the same town and n	ange, may be recorded	9 10 30 11	29 28 27	2 23 2 7 26 25 35 36	
A. Description of original monu			13			
Original corner est July 12, 1847. Set	ablished by Austi White Birch Post	n Burt, U.S. Deputy Surve	yor,			
ORIGINAL BEARING TR	EES:					
W. Pine 6" S52° W. Pine 6" S49°			EER GROUI	pplekan	£	
B. Description of corner evidence	e found and/or method ap	plied in restoring or reestablishing corn	er. Pr	6	-10-97	
No original evidence up and destroyed any been used. Roadway and a field woods li South on the East si The fence line is bathe centerline of the Location is in confo	e was found. An of evidence. The ris now growing true runs West for de of the road and rely distinguishade road and on linguishade with the company wit	old Township roadway has he coadway has never been graces & brush. A cutting lashort distance. A fended East from the apparent ble. I re-established the with the fence line runginal field notes.	peen graded aveled but ine runs l ce line run corner pos the corner uning East.	has East ns sition. in		
C. Description of monument for c	orner and accessories esta	ablished to perpetuate locating the positi	ion of the corne	PF:		
are the corner position	on 1 set a 2½"X30 untv Remonsmentst	" aluminum pipe with a 3" ion, T48N, R38W, R39W, S1	cap , S6,	EARL W. APPLEKAM PROFESSION NO. 17610	HIGAN IL	
		one reference object.	num.	APPLEKAN PROFESSION	IP ☆	
6" Triple Cedar N68' 7" Cedar N35'	?-25'W 71.27' - ?-17'E 91.56' -	9" Maple N82°-12'E 25. Steel Sign Post S45°W 1.	.24'	SURVEYO NO. 17610	R 10.6.3.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4	
Signed by Land (1)	andekan	40		* OFESSION	Property.	

Signed by <u>Car</u>

Surveyor's Michigan License No._

May 23, 1997