## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in DRTCMAGON	Located in:	Corner Code <del>-≠</del> ≠
(County)	Located III.	CONTIEN COCK
1. Public Land Su	vey T R	
	T R	
	T A	
	T R	
2. Property Contro	lling \$ <u>24</u> T <u>51N</u> A <u>37N</u>	<u> </u>
in Section	S <u>25</u> T <u>5H</u> R <u>37</u> 1	<u> </u>
3. Miscellaneous	S <u>25 T 51N A 371</u>	<u> </u>
Property in Sec	S T D	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims

i, Stephan J. Szyszkoski , in a field survey on July 07, 1992 , 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in kines it and 2 above were in conformance with regulations and rules therefore as required in the current menual of survey instructions of the United States Department of the Interior, Bursau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as appreciated below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

<u> </u>	B	C	D	6	Ŧ	G	H	1 4	K	Ĺ	М
Π			[ ]				$[ \ ]$				
Ľ	i		i —	$\Gamma$	Ī		iΠ		i		i –
							Ţ				Ţ
	<b>-</b>		i —		i –		ľ	_	'_		•
					Ţ						
<u>'</u>	•	-1	<b>)</b>	-"	•	-'	ľ	<b>—</b> 1		_	3
	Т	$\overline{}$	$\vdash$				П	П		П	_
-'	•	2	<b>9</b>	•			ì		3	2	
	П	П	П	П			П				
-3	_	-3		-2	•	-2	"—	2	•	-2	•
Н	Н	Н		П						П	
<b>⊢</b> 3		-3	•		ĺ	~	•	<b>-</b> 3	•	—3 1	•
											_

- A. Description of original monument and accessories and/or subsequent restoration:
- 5.24 (14) South 1/16 corner between Section 19, T51N-R36W and Section 24 T51N-R37W. Corner not established in original survey. Found no subsequent record.
- \$.2\$(14) South 1/16 corner between Section 30, TSIM-R36W and Section 25, TSIM-R37W. Corner not established in original survey. Found no subsequent record.
  - (7) North 1/16 corner between Section 30, TSIN-R36W and Section 25, TSIN-R37W. Corner not established in original survey. Found no subsequent record.
  - 8. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 3.24(14) Established corner midway and on a straight line between recorded corners MB and M9. Found no monumentation or evidence of use at this position.
- \$.25 (14) Estasblished corner midway and on a straight line between recorded corners N10 and N11. Found a 1.5° diameter iron pipe 4.1' West of the corner.
  - (7) Established corner midway and on a straight line between recorded corners M9 and M10. Found no monumentation or evidence of use at this position.

G. Description of monument for corner and accessories established to perpetuate locating the position of the corner: \$2.26(14) Placed a 1\*x36\* iron pipe capped \$.26(14) Placed a 1\*x36\* iron pipe capped 77) Placed a 1\*x36\* iron pipe capped with a 4° dia. cast aluminum MDNR with a 4° dia. cast aluminum HDNR with a 4° dia. cast aluminum MDMR tablet. Plazed and scribed the tablet. Blazed and scribed the tablet. Blazed and scribed the following bearing trees: following bearing trees: following bearing trees: 8" Heelock S64E 33.8" (1/16S 8T) 11° Y. Birch W23E 4.8' (1/16S BT) 7" Sugar M38E 11.8" (1/165 BT) 9" Sugar \$720 4.5' (1/165 BT) 16" Y. Birch \$30E 14.2" (1/165 BT) 9° Sugar 587E 30.4' (1/16S BT) 10° Sugar | N31N 12.6' (1/165 BT) 6° Sugar S17E 6.8' (1/165 BT) 23" Heslock \$52# 22.2' (1/16S BT) 4" Hemlock MolE 16.3' (1/168 BT) 24" Hestock | N20W 11.2" (1/16S DT) 12" Y. Birch SBIN 7.4' measured on slope Placed a 6° squared cedar post N45W 1' Squared and scribed a 4" Hestock 532E 11/165 BT). Placed a 4" smusced maple post South 1'.

Signed by Stephen J. Szyanhahi

7-14-92

----

STEPHAN J.
SZYSZKOSKI
LAND
LAND
NO. STREET BLAN
33986

CARD S