Recorded De Company 1994

at 3:30 o'clock P. M. in

Uber Stangar 3 page 244

Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims

I. Stephan. J. Szyszkoski , in a field survey on <u>August 29, 1994</u>, 19, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Quarter corner common to Sections 23-24. Corner established in 1845 by We A. Burt as follows: "Set sugar post Qr. Section corner, Sugar 8 H37E 30, do 6 H42W 21". Corner recorded pursuant to Act 74, P.A. 1970 by Reith t Sackett, Rts 819006, in 1977 as follows: "Re-established on line between Section corners. Set 1" I.D. by 5 foot long iron pipe. 6" Maple H88W 17.8' 1/4S M81, 5" Maple S79E 27.1' 1/4S M81, 6" maple M53W 1.9' squared and marked 1/4 23.24". Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

Original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Recovered the monument placed in 1977, as described, and at record bearing and distance from the 1977 accessories. Determined that the account placed in 1977 is 10.6' east and 6.8' morth of the postion proportionate to the original record, and, as it appears not to have been ratied upon since 1977, I rejected it as monumenting the 1/4 corner. Reestablished the corner on a straight line between monumented section corners, previously recorded pursuant to Act 74, P.A. 1970, and being 2623.37' morth and 2623.37' south. The 1977 monument, which bears M608 12.6' from the corner, was left in place.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 3/4" dia.x48" long aluminum rod capped with a 3 1/4" dia aluminum cap stamped: "County Remonumentation T51M R40M 1/4 23\24, 8-29-94, PS33986" from which bear the following:
10" Maple M51E 11.7" mrkd "1/4S M81" 6" Sugar S75M 24.9" do
10" Maple M25M 10.7" do
10" Asple M25M 10.7" do
netal sign post S85M 1.0"
Distances are to notch in lower blaze.
Bearings are magnetic.

STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986

ONTONAGON COUNTY
PEER APPROVED
Lack W Applehouse
Ont. Co Rep.
12-15-91-

Signed by Stephen System Date 10-5-199

Surveyor's Michigan License No. \_\_\_\_\_\_33986\_\_\_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS. JAN. 28, 1971.