Filing Requirement of Act 74, Mich. P.A. 1970

Ontonagon		Localed In:	Corner Code ≠#	
	(County)	Cocated in:	Corner Code ====	Macordal December 19 20 94
1.	Public Land Survey	T R 40M_ T R T R T R		Uber Strangy Dage 242 Con Manager dagerty Rogistar at Dayles
2.	Property Controlling	S T R		
	In Section	S T R		
3.	Miscellaneous	S T R	·	Register of Deeds Stamp & File Number
	Property in Sec.	S T R	· L	
4.	Lot No, J	Recorded Plat		
5.				
				╴├ ─╂ ╌┆ ─╂ ─┆ ─╂ ─┆ ─╂ ─┆─╂
				┦╾╃╾╃╾╂╶┼═┡═╏
				╺┟╴┼╌┼╷┼╌┼╷┼
			iaptemba <u>r 01, 1994</u> . 19 <u> </u>	
			A. of 1970, the corner points mention and rules therefore as required in	
	rrent manual of survey instr			
	nagement or by a decree of			
			d of Land Surveyors or by a Decree	
	url of Law; established, pressed below:	re-established, monumented, r	las 10 mm mm	
				25-
NC			and range, may be recorded	<u>" </u>
	on this certificate.	•		12 - 31 32 34 35 36
				13

A. Description of original monument and accessories and/or subsequent restoration:

Section common to Sections 14-15-22-23. Corner established in 1845 by Nm. A. Burt as follows: "Set Fir post corner Secs. 14,15,22,23. Cedar 12 S53E 17, Do 10 M74W 19." Distances to adjacent 1/4 corners east and south recorded by Burt as 40.02 ch. and 40.00 ch. respectively. Corner recorded pursuant to Act 74, 1970 by Reith t. Sackett for Michigan Dept. of Natural Resources in 1976 as follows: "Original aconument and accessories not found. Re-established at location pointed out by local residents. Corner falls in center of gravel road in line with fence south and old road north. Corner fits good with other corners in the area. Set 1"I.D.x24" iron pipe with 4" aluminum cap. Fence corner post S20W 30.4", Power pole W78E 134.1". Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original post and accessories have been destroyed by road and ditch construction and by cultivation. Original line call west from corner "1.50 Enter swamp C. N&S" is obliterated by same. Recovered and accepted the 1"I.D.x24" iron pipe, anchored firmly in the road surface by a reinforcing rod cross-piece through the base, with only the stem of the aluminum cap remaining in the pipe. The cap itself was apparently sheared off by a plow or road grader. The pipe appears in good condition and is set vertically. The 1976 accessory power pole was found at record bearing (corrected for secular variation). The fence corner post was found at record bearing but 31.4" distant. I removed the stem of the aluminum cap, drove the pipe to 6" below the gravel surface, and firmly wedged into it a 2.5" length of 3/4" dia. aluminum rod, split at the bottom, capped with a 31/4" dia aluminum cap, center punched, and stamped to read "County Remonumentation 751M R40N 14 15 22 23, 9-1-94, PS 33986". I found the distances east and south to adjacent 1/4 corners remonumented in 1976 by Keith L. Sackett to be 39.934 ch. and 39.859 ch. respectively.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Drove capped aluminum rod described above into the 1976 i I.D. iron pipe. Set nails with brass MDMR REFERENCE tags in the following (brgs magnetic): 7 Sugar SILE 47.63 mrkd \$23 MBT Power pole, unnumbered, MBIN 236.36', nail is 5.5' above grnd. Power pole, unnumbered, MBZE 134.35', nail 4' above grnd. 6 cedar corner fence post \$23N 31.32'. Metal sign post \$35E, 34.7'.

STEPHAN J. SZYSZKOSKI LAND SURVEYOR NO. 33986 ONTONAGON COUNTY
PEER APPROVED

Earl W Applikangs Out Go Rep. 12-15-92