REMESHIE ELECTRICA PRESQUE ISLE COUNTY STATE OF MICHIGAN RECORDED 94 SEP 12 AM 10: 40 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in not M. Samp Presque Isle Located In: Corner Code ## (County) 7 36N R 2E 1. Public Land Survey R. LIBER 311 PAGE 233 R R **Property Controlling** in Section R Miscellaneous S Register of Deeds Stamp & File Number Property in Sec. R \_\_ , Recorded Plat \_ 5. Private Claims \_\_ James A. Beck in a field survey on July 13 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 A. Description of original monument and accessories and/or subsequent restoration: Original monumentation in Government Resurvey. Set post corner of Sections 25 & 36 and referenced: Aspen 12" N50'W 27 Links W. Pine 12" S19'W 21 Links Corner Recorded by
Ronald R. Bischer,
P.S. 22428. Nov. 8, 1979,
Set 1/2" rod by single proportion on
Township Line. Referenced:
N28'E 46.87' 6" Balsam
S43'W 17.36' 4 Maple
N70'W 16.26' 3" Maple Notes from survey (circa 1955) of Sec. 30, T36N, R3E by Doyle Engineering furnished by James Granger of Granger Associates Found 4" x 4" Cedar Stake Ratified by Peer Group in accordance with P.A. 34 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Chairman Delmus Porte M-11 Date August 29 1094 found a 2" pipe by extenting line from corners M-9 (NE Corner Sec. 25) to M-10 (East 1/4 Corner Section 25) these being corners as noted by Doyle Engineering in work performed in Sec. 30, T36N, R3E, circa 1955.

Corner was discovered after running traverse from SE Corner Sec. 25 (M-11 per 1979 recordation) to NE cor. (M-9) per 1975 recordation. Doubling back from iron pipe found at E 1/4 Cor (M-10) produced a 2" erect pipe with 4"x4" rotted post prone upon the surface covered with humus adjacent to the corner. Southwest of corner approximately 13'. a 1994: Southwest of corner approximately 13', a rotted pine stump was found, possibly original bearing tree. Computations of corner relative positions along Easterly line Sec. 25 using this corner are in near exactness to singular proportionate measure and alignment. This corner monument location is believed to represent and supercede corner recorded by R. Bischer refered to in an obversely position of monument for corner and accessories established to perpetuate locating the position of the corner. M-1 1 /2" iron rod and cap P.S. 21559 inside a 2" is pipe with coupling. tnesses:

S23'W 13' (approx.) Rottes Pine Stump N18'W 8.19' 7" Maple \*

S62'E 42.50' 3" Maple\*

S03'E 10.00' 8" Stem of Twin 6" —8" Maple OF MICHIE 1994: s:
13' (approx.) Rotted Pine Stump
8.19' 7" Maple \*
42.50' 3" Maple\*
10.00' 8" Stem of Twin 6"—8" Maple
21.56' 5" Maple \*
13.02' 1/2" Iron Rod (at previously JAMES A **BECK** LAND SURVEYOR previously re-rner location) No. corner 21559 Set tag P.S. 21559 Date August 25, 1994 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Surveyor's Michigan License No. . 21559 REVISED MAY 14, 1975 REVISED JAN., 1983

2459