11714

LAND CORNER RECORDATION CERTIFICATE

For corners in	
Roscommon Located in: Corner Code # FILE IN LIBER 3 OF LAND CORNERS (County) FILE IN LIBER 3 OF LAND CORNERS STATE OF MICHIGAN RUSCOMMON COUNTY	.S
1. Public Land Survey T21N R01W T R SURVEY & 29 DEC 98 2:17 P.M. 2. Property Controlling in Section S T R in Section S T R Property in Sec. S T R SECTION RECORDED RECORDED	er
4. Lot No, Recorded Plat	
5. Private Claims I,Timothy L Lapham, in a field survey on _September_, 19 _ 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the function of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan for the Michigan for the Michigan for Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, found as expressed below:	12
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate	
10 30 29 28 27 26 2 11 12 31 32 33 34 35 35	36
A. Description of original monument and accessories and/or subsequent restoration:	
M-6: GLO 2/13/1837 J Brink -post Hemlock 10 \$28-1/2W 35 Beech 10 N71W 34 Roscommon Co. LCRC 2-12 date and surveyor unknown 1-1/2" pipe with post - in clearing, no trees near Survey 11/6/1961 G Henning Found 1-1/2" pipe in clearing, no trees near Section break 1989-90 D Ledy - Found 2" pipe NE 1.72' spike in 6" Twin	y
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-6: Found 1-1/2" pipe 24" above grade at single strand fence north and south and approximately 66' west of the remains of an old fence. Drove pipe down to 8" above grade. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: distance measures 26.73'. Accepted found pipe as best evidence of the correct position of the corner. The remains of an old fence. Drove pipe down to 8" above grade. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: distance measures 26.73'. Accepted found pipe as best evidence of the correct position of the corner. The remains of an old fence. Drove pipe down to 8" above grade. The remains of an old fence of the corner. The remains of an old fence of the corner. The remains of an old fence of the corner. The remains of an old fence of the corner. The remains of an old fence of the corner. The remains of an old fence of the corner. The remains of an old fence of the corner. The remains of an old fence of the corner. The remains of an old fence of the corner. The remains of an old fence of the corner. The remains of an old fence of the corner.	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-6: Set 5/8"x36" rerod with aluminum Ogemaw County remon cap inside found 1-1/2" pipe. Witnesses: N54E 26.73' NAIL IN 8" TWIN POPLAR (OBT) N52W 14.36' NAIL IN 4" POPLAR (OBT) S07W 63.58' NAIL IN 10" POPLAR S56E 48.00' NAIL IN 12" TWIN POPLAR (OBT) South 1'+/- carsonite post Date /2/21/4 8	
Surveyor's Michigan License No. 27595	

LIBER 3 PAGE 561