SURVEY & REMONUMENTATION

2926

OCT 0 5 1998

LAND CORNER RECORDATION CERTIFICATE SECTIONING Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN ROSCONNON COUNTY RECORDED

For cor	ners in			20 APR 98 2:19 P.M.
Rosc	(County)	Located In:	Corner Code #	ROBERT W. SMITH REGISTER OF DEEDS
1. Publ	ic Land Survey	T 24N R 1W T 23N R 1W T R	<u>l-13</u>	To be filed in Liber 3 of Land Corners
in Se 3. Misc	perty Controlling ection ellaneous perty in Sec.	TR STR STR STR		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims				
t. Marvin E. Myers , in a field survey on March 2 , 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States. Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.				
NOTE: Not more than 2 corners, all in the same town and a on this certificate.		n and range, may be recorded	11 12 31 32 33 34 35 36	
A. Description of original monument and accessories and/or subsequent restoration:				
L13	G.L.O - 1838 Lewis Clas Mon Post 10" W. Pine N53°E 15 lk 7" Spruce N55°W 22 lks	Michigan Dept. of Conservation 153°E 15 liks. Mon: Found or established, and replaced		L. 2, Pg. 465 Mon Axle Shaft in Center Line N-S Road 5" Tamarack N66°W 93.7" 6" Tamarack N22°E 90.4"
	L. 1, Pg. 101 (Herbert L. P.S. #18223 9-11-1974) Mon Found Gear Shaft P.P. N75°W 43.80	••	L. 1, Pg. 155 (Frank J. Arleth P. April 2, 1975) Mon Found 1 ¹ Axle Shaft Nails in:	PEER GROUP APPROVAL DATE MARCH 279-1998

Mason E. Myen MEM 6" Tamarack N30°E 90.5"

B. Description of corner evidence found and/or method applied in restoring or reestablishing cornegunty Surveyor Found 1 1/4" axle shaft in Monument box in the centerline of F97 (St. Helen Road) and 200'± South of the centerline of Marl Lake Road Found spike in Southwest face Power Pole N72°W 43.90'

P. Pole N80°W 43.8'

No other accessories were found. Accepted as the best available evidence of the position of the Original Corner. Replaced 11/4" x 36" axle shaft with standard Roscommon County monument in monument box in centerline of F-97.

C. Description of monument for corner and accessories established to perpetuate locating the maintain of the corner:

Mon - Standard Roscommon County Monument in monument box.

Wit: Set carsonite post 33' East.

5" Poolar N50°E 50.69"

9" Baisem N30"E 90.45"

Found spike in Southwest face Power Pole N72°W 43.90' Set nail & tag in Southeast face 8" Poplar N52°E 50.43' Face of highway R.O.W. marker S50°E 41.49' Set nail & tag in Southwest face 10" Tammarack S19°E 101.45'

LARVIN E LIVERS OFE88ION SURVEYO OFESSION 10, 1998

Date April 10,

Surveyor's Michigan License No. 31606

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS SED MAY 14, 1975 EVISED JAN., 1983 EVISED OCT., 1996

LIBER 3 PAGE 499