SURVEY & REMONUMENTATION

MAY 28 1997

9571

Property in Sec.

4. Lot No. _____, Recorded Plat _

COMMISSION

STATE OF HICHIGAN ROSCOMMON COUNTY RECORDED

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

23 DEC 96 10:45 A.M.

ROBERT W. SHITH REGISTER OF DEEDS

For corners in Corner Code # Located in: Roscommon T24N R 2W <u>E6</u> 1. Public Land Survey 2. Property Controlling in Section Miscellaneous

Register of Deeds Stamp & File Number

5. Private Claims I, <u>Craig W. McVean</u>, in a field survey on <u>July</u>, <u>1996</u>, do he state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner , 1996, do hereby points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a

decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established,

monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - E6 Set 1/4 Sec. Post Wm. Burt 1852
 - S. Pine 8" S 3/4°W 882 Lks.
 - Cedar Post, Placed Midway in Line G.F. DeLaMater -1929
 - S. Pine 8" N51°E 100.6"
 - S. Pine 8" S50°W 90.2"
 - MDNR Airport Hanger Lot Survey E6 Iron Pin T.R. Tucker 1949
 - RCRC Rd. Plan 1967 No Corner noted.



- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- E6 1/4 Corner common to Sec. 16 & 17 Found no evidence of Iron Pin. GFD J. Pine stump with his tag in blaze with BT Scribe to SW. Excavate at proportional and WigLocation in CL. of N-S Rd. Dig Down 2' and find nail with flagging at old road base level. Nail doesn't fit airport hanger survey so we reject position. Dig down 3.5' but find no other evidence. Set 1" x 32" Iron Pipe w/4" Alum. Cap in Mon. box at record Dist. from Wit, Stump and straight line between E5 & E7 at CL. of N-S Rd. Monument fall 0.55' S of Single Proportional Position and fits airport hanger lot survey within 0.3'. Monument accepted as a careful and faithful re-establishment of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: ROSCOMMON COUNTY

E6 - 4" Alum Cap on 1" x 32" Iron Pipe in Mon. Box.per Part B.

S16°E 108.71' to N&T in E. Side 4" J. Pine Scribed' X BT' S18°W 113.11' to N&T in E. Side 6" B. Oak Scribed' X BT' N38°W 80.03' to N&T in E. Side 6" J. Pine Scribed' X BT'

S50°W 90.2' to N&T in scribed BT Blaze of 10" J. Pine Stump (GFD)

PEER GROUP APPROVAL

DATE A46-16, 1998 marin E. Myen Mille

Marvin E. Myers, P.S.

County Surveyor

Surveyor's Michigan Li

N55°E 69.13" to 1/2 x 18" Rebar - Down 1

West 33' to Carsonite Post

Date 11/26/96