LIBER 2 PAGE 60

REMONUMENTATION LAND CORNER

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

			AND 1888 A	_ ~ ~ *
<u>የተውሞተ</u>	/ED		DEG	וטחי
RECEIV	V F 1.3	T UIIX	ILL	$\partial \mathbf{O} \mathbf{M}$
The state of the s				. , , . ,

95 SEP 27 AM 8: 48

IBER NO. 2	PAGE NO. 60
ESTH REGISTER	ER LEE OF DEEDS D. MICHIGAN
SANILACC	D., MICHIGAN

	Sanilac	Located In:	Corner Code ##
	(County)	Located III.	Comer Code
1.	Public Land Survey	T 10N R14E T R	K-5 L-5
_	5	TR	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

Register of Deeds Stamp & File Number

4.	Lot No	Recorded Plat
5.	Private Claims	i

John A Milletics, in a field survey on April 16, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
 K = 5
 I. = 5

K - 5
GLO Notes
Set Post Maple 20 N46W 19
Beech 9 S71½E 25
Act 74 None
Act 132 None
Road Comm None
Drain Comm None

GLO Notes

Set Post at 39.66 Chains

B. Ash 12 N812E 20

Birch 6 S2W 9

Act 74 None

Old Survey Liber None

Road Comm None Drain Comm None

Approved Peer Board Meeting Sept 27, 1995

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-5

For corners in

SE Corner Section 11 T10N-R14E

L - 5

S 1/4 Corner Section 12 T10N-R14E

Found R/R Spike 4" Deep in Pavement Found no sign of corner

SUHVEY & GITATION

OCT 2 6 1995

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K - 5
SE Corner Section 11 T10N-R14E
Moun Box
N45W 73.2 to a nail in a Power Pole
N30W 52.5 to a Stop Sign
S40W 44.4 West end of a 24" CMP
S45E 45.0 East end of a 24" CMP

L - 5 S 1/4 Corner Section 12 T10N-R14E Monu Box

NO5°E 51.8 to a nail in a Power Pole N40°W 44.4 North end of a 18" CMP S40°W 36.3 South end of a 18" CMP

North 5.8 to the centerline of pavement Set moru at half distance between corners half distance being 2617.00

	Ol small
Signed by	ama Millione

Date <u>Sept 11, 1995</u>

Surveyor's Michigan License No. _____

25859

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1915 REVISED JAN., 1983