

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

94 AUG 12 PM 2:38

For corners in

LIBER NO. 1 PAGE NO. 465  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

Sanilac (County) Located In: Corner Code ##

1. Public Land Survey	T 10N R 15E	M - 6, M - 7
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2							
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, John A Milletics, in a field survey on July 12, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- M - 6 Found 1/2" iron bar in gravel road, per survey dated 8-05-80 Sanilac Land Surveying
  - M - 7 Found 5/8 Iron Bar in paved surface, per survey dated 8-05-80 Sanilac Land Surveying

Approved Peer Board Meeting  
Aug. 9, 1994 *[Signature]*

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M - 6  
E 1/4 Corner Section 13 T10N-R15E  
Found 1/2" Iron bar
  - M - 7  
SE Corner Section 13 T10N-R15E  
Found 5/8" Iron Bar

SURVEY & REMONUMENTATION

SEP 07 1994

COMMISSION

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- |  |   |
|--|---|
| M - 6<br>E 1/4 Cor Section 13 T10N-R15E<br>1/2" Iron Bar<br>S30°E 103.8 to a nail W side of a 24" Maple<br>N30°E 112.5 to a nail SE side of a Tele Pole<br>East 33.00 to a 1/2" Iron<br>South 2639.44 to the SE Cor of Sec. 13 | M - 7<br>SE Cor Section 13 T10N-R15E<br>Monu Box<br>N45°E 38.7 to a nail SE side of a Fence Post<br>N40°W 40.8 to a nail NE side of a Guard Rail Post<br>S45°W 87.2 to a nail NW side of a Anchor Pole<br>West 2643.0 to the S 1/4 Cor Section 13 |
|--|---|

Signed by *[Signature]* Date July 23, 1994  
Surveyor's Michigan License No. 25859