REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94	AUG	12	PM	2:	36

For corners in	,			
Sanilac (County)	Located In:	Corner Code #		
1. Public Land Survey	T 10N R 16E	I - 13, H - 13		
Property Controlling in Section	T R S T R S T R			

____T___R__

ESTHER LEE

REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

4.	4. Lot No, Recorded Plat	
5.	5. Private Claims	

John A Milletics , in a field survey on July 18 1994 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 I 13 Found 5/8" Iron Bar in gravel road bed, as per
 Survey dated Jan 2, 1979 Sanilac Land Surveying
 - $\rm H$ 13 Found 5/8" Iron Bar in gravel road bed as per Collins Survey

	A	В	c	D	E	F	G	н	ı J	к	L	М
2		6	L	5 —		4		3	:	2	1	
3	<u> </u>	_	↓_		_	_	<u> </u>					
4	L	ļ 	-	 8	L	 	<u> </u> _1	0	1	[1—	1	2_
5	ļ	<u> </u>	<u> </u>	_		Ļ_	L	_				Щ
6	Ļ	18	ļ_,	7	ļ_,	6	<u> </u>	5	1	4—		3_
7	L	<u> </u>	<u> </u>	┖	<u> </u>	ļ	<u> </u>		<u> </u>			L
8	_	 19—	2	 	L.,2	 !1	L_2	2	2	3—	2	4
9	Щ	ļ_	↓_	L.		<u> </u>	<u> </u>		<u> </u>			
10	<u> </u> ;	 30—	-2	 9	_2	 28	2	7	2	6—	<u></u> 2	5
11	L	ļ.,	_			<u> </u>	L					
12	<u> </u>	 31—	<u> </u> _;	2	ļ.	3—	 3	4	_3	5		6-
13	L		ł	1		1				L		

Approved Peer Board Meeting Aug. 9, 1994 R. J.

gn

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I - 13

Miscellaneous

Property in Sec.

SE Cor Section 34 T10N-R16E Found 5/8" Iron Bar

H - 13

S 1/4 Cor Section 34 T10N-R16E

Found 5/8" Iron Bar

SURVEY & REMONUMENTATION

SEP 07 1994

COMMISSION

C	Description of monument	for corner and accessories	established to perpetuate	locating the position of the corner:

I - 13

SE Cor Section 34 T10N-R16E

5/8" Iron Bar

NO5°W 96.10 to a nail E side of a Power Pole N40°E 119.0 to a nail E side of a Power Pole East 25't to the centerline of a gravel road to the north.

S60°W 57.60 to a nail NW side of a 18" Poplar

H - 13

S 1/4 Cor Section 34 TlON-R16E

5/8" Iron Bar

S05°W 31.30 to nail E side of a 24" Maple S30°E 40.40 to a nail W. side of a 24" Maple S30°W 38.10 to a nail W. side of a 12"Pine

North 54.80 to a nail W. side of a Power Pole

Signed by John Full Surveyor's Michigan License No. 25859

Date July 24, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975