REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE 93 DEC 28 AM 10: 39

For	r corners in	Filing Requirem	ent of Act 74, Mich. P.A. 197	IBER NE SEAR RIEE	
	SANILAC	La subsidilar	1	t D i Die De Tree to S	
	(County)	Located In:	Corner Code =##	REGISTER OF DEEDAN SANILAC CO . MICHIGAN	
1.	Public Land Survey	T10N R 16E T R T R	H - 1,(I - 1)		
2.	Property Controlling in Section	T R S T R S T R			
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number	
	Property in Sec.	S T R			
	i ei Ne	Described Dist			
		Recorded Plat	· ·	A B C D E F G H I J K L M	
O.	Tivate Olamb		N 4	2 - 5 - 4 - 3 - 2 - 1 - 1	
				3	
	T 1 1 200 4 7 1			4 7 7 8 9 10 10 11 12 12	
I, John A Milletics, in a field survey on <u>Dec 23</u> , 19 1993, 5 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned					
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					
		ith the rules of the Michigan Board of L		8 - 19 - 20 - 21 - 22 - 23 - 24 - 9	
	urt of Law; established, pressed below:	re-established, monumented, re-mor	numented, recovered, found as	10 30 30 30 37 36 35	
		corners, all in the same town and	ranga may be recorded	11	
NO	on this certificate		range, may be recorded	12 31 32 33 34 35 36	
			<u>₹</u> 1	13	
A.	Description of original	monument and accessories and/o	r subsequent restoration:		
	H-1				
Found $1/2$ " iron bar in gravel road bed, per iron found in survey dated $1-20-1988$.				n survey	
			···		
I - 1 Found 1" iron bar in gravel road bed, per iron bar found					
		on bar in gravel road bed nilac Land Surveying.	i, per iron bar found o	on survey dated	
В.		Description of corner evidence found and/or method applied in restoring or reestablishing corner: - 1			
H-1 N 1/4 Cor Section 3		n 3 T10N_D16F	NE Cor Section	3 T10N-R16E	
	Found 1/2" iron		Found 1" iron be		
	round 1/2 11011	vai	round a aron or		
				REMONUMENTATION	
				4000	
				1993	
				and saster the SA	
			•	COMMISSION	
			•		
C. Description of monument for corner and accessories established to perpetuate locating the position of				the position of the corner:	
	H - 1		T - 1		
	-	tion 3 TION-R16E NE Cor Section 3 TION-R16E			
	1/2" iron bar		1" Iron Bar		
	South 75.12' to a nail in a thorn apple tree N10°E 15.40' to the East leg of a road sign			the East leg of a road sign	
	S20°E 24.40' to the East end of a 12"CMP N50°W 38.75' to a nail in a Tele Pole S30°W 29.20' to the West end of a 12"CMP S45°E 51.65' to a nail in a cable route si				
	East 2608.22 to	ast 2608.22' to the NE Cor of Section 3 West 2608.22' to the N 1/4 Cor Section 3			
	01	1 most			
Sia	ned by	H. I'llelics	DateDe	c 24, 1993	
⇒,	veyor's Michigan Licen	se No. 2585	9	F'	
-501	veyor a wiicingan Licen		FORM A	PPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983	