APR 1 4 1998

2 PAGE 151 UBER

SECTION

1997 REMONUMENTATION

RECEIVED FOR RECORD 97 DEC -2 AM 9: 08

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER HO 2 PAGE HO 151 REGISTER OF DEEDS SANILAC CO. MICHIGAN

For corners in AUSTIN TOWNSHIP

SANILAC Located in: Corner Code # (County) 1. Public Land Survey T14NR T_14NR_13E R 2. Property Controlling R in Section 3. Miscellaneous Property in Sec.

SURVEY & REMONUMENTATION

JAN 0 8 1998

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _, Recorded Plat 5. Private Claims

I, John A. Milletics in a field survey on Oct. 4, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

3 R 9 1

A Description of original monument and accessories and/or subsequent restoration:

Cl1 . . . G.L.O. Notes set post cor. Sec!s. 29, 30, 31 & 32 Beech 12 S30E 13, Hemlock 18 N36W 32 Act 74 Form - None Act 132 Form - None Road Commission Record - None Drain Commission Record - None

C10G.L.O. Notes Set 1/4 Section Post Hemlock 10 S34E 4 Birch 10 N51W 19 Act 74 Form - None Act 132 Form - None Road Commission Record - None Drain Commission Record - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Cl1
Found 1/2" Re-Rod in Monument Box John A. Milletics ** C10 Milletics Post in the Second Land Surveyor No. 25859 0/0 solono: 8111

1/4 Cor. Sec's. 29 and 30, T14N-R13E

East 57.15' to Spike in N. Side P.P.

Found 1/2" Re-Rod in Monument Box

S40°E 40.85' to 1/2" Steel Stake

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. C10

Cor. Sec's. 29, 30, 31 and 32, T14N-R13E

Found 1/2" Re-Rod in Monument Box

WITNESSES:

N70°E 75.94' to P.K. Nail in N.W. Side Tel.

Ped Post

S45°E 37.48' to 1/2" Steel Stake

\$45°W 52.37' to 1/2" Steel Stake N45°W 69.47' to Spike in N.E. Side P.P.

North 2649.66' Cl0, Tl4N-Rl3E South 2650.28' 1/2" Re-rod apparent Cl2, Tl4N-Rl3E and Milleton Signed by

West 49.40' to P.K. Nail S. Side Cor. Post

WITNESSES:

N40°W 40.82' to 1/2" Steel Stake North 2643.06' C9, T14N-R13E

South 2649.66' Cl1, Tl4N-Rl3E

Nov 12, 1997 Date

Surveyor's Michigan License No. 25859

PEER GROUP APPROVED

AT MEETING HELD

NOV. 26 /1, 1997.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995