## SCHOOLCRAFT COUNTY PEER GROUP APPROVED

## DATE Mat 12,1995 CLAND CORNER RECORDATION CERTIFICATE

JAN 3 0 1996 COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in

	i conicio in											,				
₋S	choolcraft County)	Located In:		Corne	Corner Code ##			Received & Filed this day of								
1.	Public Land Survey		T 42 N R 15 W T 42 N R 14 W T R T R		1-7	Sigrid I. Hedberg Schoolcraft Co. Reg. of Deeds										
2.	Property Controlling	s	_ T R													
	in Section S T R															
3.	Miscellaneous	P.o.	gister d	st Da	ade C		e Eile	. Al								
	Property in Sec.	n eş	gister t	<i></i>	eus c	tanip	or rile	NUIT	iber	-						
															_	
	Lot No.					·		вс	. D	E F	GН	1 1	к	L	м	
5.	Private Claims							ΠΠ		٠.		1		Ť	٦	
							2 <del> </del> _	6	— 5 I	4-	<del> </del> 3−	1-2	+	i -	1	
							3	+			╅╌╁╾	+-+	+		4	
I, Thomas P. O'Brien , in a field survey on Nov.7 , 19 95								<del>!</del> —	k	ģ	<del>-</del> i⁄	+-₫		-12-	$\dashv$	
								╁┈┷	_}_	<del>} - } -</del>	+	┵┵	-+	+	4	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the								18	17	16	  15			 13-	ᅬ	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land												11		Ī	1	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5								<u> </u>						I	7	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a								ï	20	-21-	1-22-	1-23	<u> </u>	2 <b>4</b>	1	
Court of Law; established, re-established, monumented, re-monumented, recovered, found as							9	† †	_†_			+-+	十		1	
expressed below:							10	30-	—2 <del>'9</del>	28	27~~	26	<del>}</del>	-25-	-{	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded								╂╼╾╁		-	+ +	+-+	$\dashv$		4	
	on this certificat	ie.					12	31	3 <sup>2</sup>	33_	34-	<del>  3</del> !	<u>;</u>	—36~	4	
							13	11			$\perp \perp$	$\perp \downarrow$			╛	
A.	Description of original	al monument	t and accessories a	nd/or subsec	quent restoratio	on:										
M·	-7 (S.E Corner : Sept. 10, 18: Cedar 7 in. 1	50 Algerr	non Merryweath inks Spruce	er D.S. s 10 in. S	set corner 1 662W 65"	post.										
	April 19/51	Algernon	Merryweather	D.S. Corn	er 18&19 W	est Bour	ndarv	-								

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Cedar 16 in. N35E 26 lks. Tamarack 16" S88E 14"

Jan.8, 1957 Billy D. Buckler, RLS found 2½" iron pipe with brass cap set by Carl Christensen.

Oct.19, 1994 Thomas P. O'Brien, PS recovered iron pipe w/brass cap set by Carl Christensen from 2 original witness trees "Cedar 16in. N35E 26 lks. Tamarack 16" S88E 14" as noted in County Surveyors book.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- M-7 2" iron pipe w 2%" brass cap stamped to identify by "CC". Witnesses: (previous witnesses by B. Buckler have been cut.) 10"Cedar N30°W 14.45' 12"Cedar N82°W 31.60'

6"Cedar S31°W 19.65'

Post South 1.5'

Thomas P.O'Brien, PS

. PAGE: \_/O

Dec.4, 1995

Surveyor's Michigan License No. 21274