## SURVEY & REMONUMENTATION

## SCHOOLCRAFT COUNTY

FEB 0 8 2001

Comparison of the Comparison	PEER GROUP APPROVED  LAND CORNER RECORDATION CERTIFICATION	ATE SECTION
1. Public Land Survey  T 42Ng14W T 33Ng14W T R  1. Public Land Survey  T 42Ng14W T R  1. Poperty Controlling S T R  2. Property Controlling S T R  3. Miscellaneous S T R  Property in Sec. S T R  1. Thomas P. O'Brien, in a feet survey on 10/30/00/18: to hereby state that under requirements of PA 74 Medigan PA of 1970, the contex points mentioned in lines 1 and 2 above were in conformance with requisitions and rules therefore as required in the current narveal of survey instructions of the United States Department of the Hindro, Surveyor or by a Boxes of a Court of tawned for that the corner points mentioned in lines 3, 4 and 3 above were in conformance with the currence of the Mentional Board of land Surveyors or by a Boxes of a Court of tawned for that the corner points mentioned in lines 3, 4 and 3 above were in conformance with the current of the Hindro, Surveyor and by a Boxes of a Court of tawned for that the corner points mentioned in lines 3, 4 and 3 above were in conformance with the current of the Mentional Board of land Surveyors or by a Boxes of a Court of tawned for the Mentional Board of land Surveyors or by a Boxes of a Court of tawned for the Mentional Board of land Surveyors or by a Boxes of a Court of tawned for the Mentional Board of land Surveyors or by a Boxes of a Court of tawned for the Mentional Board of land Surveyors or by a Boxes of a Court of tawned for the Mentional Board of land Surveyors or by a Boxes of a Court of tawned for the Mentional Board of land Surveyors or by a Boxes of a Court of tawned for the Mentional Board of land Surveyors or by a Boxes of a Court of tawned for the Mentional Board of land Surveyors or by a Boxes of a Court of tawned for the Mentional Boxes of the Surveyors or by a Boxes of the	DATE 10/10/00 Total Filling Requirement of Act 74, Mich. P.A. 19	
1. Public Land Survey  T43Pig14W T37 TR  T4R T4R T1R T1R T1R T1R T1R T1R T1R T1R T1R T1	(County) STUKID NED	ÖLCRAFT CO.REGISTER
2. Property Controlling S T R S IN Scallon S T R S IN Scalloneous S IN Scalloneou	1. Public Land Survey T 42NR14W G1 JL V Date 1	1
1. Thomas P. O'Brien, in a feet survey on 10/30/00x6x. do hereby state that under requirements of P.A. 74. Mchigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with requisitions and rules therefore as required in the current manual of survey instructions of the United States Department of the Indirect, Dures out India Management or by a decree of a court of Law and of the Mchigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  Oct. 20, 1850 Algermon Merryweather, DS section corner Sections 3,4  Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 In N47E 45 birch 28 N60W 22  Dec. 28, 1961 Billy D. Buckler, RIS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.  Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument stamped to identify.  Witnesses:  26" Maple N23"E 29.70' Road Sign S11"E 43.83' 14" Maple N25W 43.47' 24" Maple S56 W 69.38' - exsisting Buckler BT - Good distance.  5 "FORESSIONAL" S=  PORESSIONAL S=  THOMAS P. Witnesses:  5 "FORESSIONAL" S=  THOMAS P. Witnesses:  5 "FORESSIONAL" S=	T R  2. Property Controlling S T R  in Section S T R  3. Miscellaneous S T R	Register of Deeds Stamp & File Number
Thomas P. O'Brien, in a field survey on 10/30/00 x18x do hereby state that under requirements of PA.74. Michigan PA. of 1970, the corner points mentioned in fines 1 and 2 above were in conformance with requisitors and regulations and regulations and regulations and regulation in the surveyors of by a Decree of a Court of Law, established, re-established, monumented for covered, found as expressed below.  NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.  Oct. 20, 1850 Algermon Merryweather, DS section corner Sections 3,4 Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 in N47E 45 birch 28 N60W 22  Dec. 28, 1961 Billy D. Buckler, RIS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.  Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument stamped to identify.  Witnesses:  26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47' 21" Maple S56W 49.38' - exsisting Buckler BT - Good distance.  5 "FROESSIONAL" S1		ARCDEFGHIJKL
Thomas P. O'Brien, in a field survey on 10/30/00 Nex. do hereby state that under requirements of P.A.74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interfore, Bursano I and Management of by a decree of a Court of Law and of that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a decree of a Court of Law, established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, at in the same town and range, may be recorded on this certificate.  A. Description of original morument and accessories and/or subsequent restoration:  Oct. 20, 1850 Algermon Merryweather, DS section corner Sections 3,4  Sugar 16 in S73W 55 Links Sugar 9 in S33E 15 Links Sugar 16 In N47E 45 birch 28 N60W 22  Dec. 28, 1961 Billy D. Buckler, RLS "This corner was replaced 50 Links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner:  Schoolcraft County monument stamped to identify.  Witnesses:  26" Maple N23° E 29.70' Road Sign S11° E 43.83'  14" Maple N256° W 90.38' - exsisting Buckler BT - Good distance.  Expreceded:  55 FereforesionAl SE	5. Private Claims	
requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current menual of survey instructions of the United States Department of the Interior, Surveya or by a Decice of a Court of Law and for that the corner points mentioned in lines 3, and 35 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decice of a Court of Law, established, re-established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A Description of original monument and accessories and/or subsequent restoration:  Oct. 20, 1850 Algernon Merryweather, DS section corner Sections 3,4 Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 In N47E 45 birch 28 N60W 22  Dec. 28, 1961 Billy D. Buckler, RLS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.  Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument stamped to identify.  Witnesses:  26" Maple N23°E 29,70' Road Sign S11°E 43, 83' 14" Maple S56" 80, 38' - exsisting Buckler BT - Good distance.  15 proofessional Section	•	
requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current menual of survey instructions of the United States Department of the Interior, Surveya or by a Decice of a Court of Law and for that the corner points mentioned in lines 3, and 35 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decice of a Court of Law, established, re-established, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A Description of original monument and accessories and/or subsequent restoration:  Oct. 20, 1850 Algernon Merryweather, DS section corner Sections 3,4 Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 In N47E 45 birch 28 N60W 22  Dec. 28, 1961 Billy D. Buckler, RLS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.  Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument stamped to identify.  Witnesses:  26" Maple N23°E 29,70' Road Sign S11°E 43, 83' 14" Maple S56" 80, 38' - exsisting Buckler BT - Good distance.  15 proofessional Section	Thomas P. O'Brien, in a field survey on 10/30/00 to do hereby state that under	4 7 - 8 - 9 - 10 - 11 - 12
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  Oct. 20, 1850 Algermon Merryweather, DS section corner Sections 3,4 Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 in N47E 45 birch 28 N60W 22  Dec. 28, 1961 Billy D. Buckler, RLS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.  Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" from bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument stamped to identify.  Witnesses:  26" Maple N23°E 29, 70' Road Sign S11°E 43.83' 14" Maple S56 W 90, 38' - exsisting Buckler BT - Good distance.  THOMAS P. THO	requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	5
Board of Land Surveyors or by a Decree of a Court of Law. established, re-established, monumented.  NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  Oct. 20, 1850 Algernon Merryweather, DS section corner Sections 3,4 Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 in N47E 45 birch 28 N50W 22  Dec. 28, 1961 Billy D. Buckler, RLS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.  Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuale locating the position of the corner. Schoolcraft County monument.  C. Description of monument for corner and accessories established to perpetuale locating the position of the corner. Schoolcraft County monument.  C. Description of monument for corner and accessories established to perpetuale locating the position of the corner. Schoolcraft County monument.  C. Description of monument for corner and accessories established to perpetuale locating the position of the corner. Schoolcraft County monument stamped to identify.  Witnesses:  26" Maple N23°E 29.70' Road Sign Sil°E 43.83' 14" Maple N25W 43.47' 24" Maple S56°W 69.38' - exsisting Buckler ET - Good distance.  Experience of the corner of t	United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	
NOTE: Not more than 2 comers, at in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  Oct. 20, 1850 Algermon Merryweather, DS section corner Sections 3,4 Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 In N47E 45 birch 28 N60W 22  Dec. 28, 1961 Billy D. Buckler, RLS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" from bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument stamped to identify.  Witnesses:  26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47' 24" Maple S56°W 69.38' - exsisting Buckler BT - Good distance.	Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented,	
on this certificate.  10 30 29 28 27 26 25 11 12 31 32 33 34 35 36  A. Description of original monument and accessories and/or subsequent restoration: Oct. 20, 1850 Algernon Merryweather, DS section corner Sections 3,4 Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 In N47E 45 birch 28 N60W 22  Dec. 28, 1961 Billy D. Buckler, RLS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner: Schoolcraft County monument stamped to identify. Witnesses: 26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47' 24" Maple N25W 69.38' - exsisting Buckler BT - Good distance.		
A. Description of original monument and accessories and/or subsequent restoration:  Oct. 20, 1850 Algernon Merryweather, DS section corner Sections 3,4 Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 In N47E 45 birch 28 N60W 22  Dec. 28, 1961 Billy D. Buckler, RLS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument stamped to identify. Witnesses: 26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47' 24" Maple N25W 43.47' 24" Maple S56°W 69.38" - exsisting Buckler BT - Good distance.	·	
A. Description of original monument and accessories and/or subsequent restoration:  Oct. 20, 1850 Algernon Merryweather, DS section corner Sections 3,4 Sugar 16 in 873W 55 links Sugar 9 in 833E 15 links Sugar 16 In N47E 45 birch 28 N60W 22  Dec. 28, 1961 Billy D. Buckler, RLS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.  Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument stamped to identify.  Witnesses:  26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.83' 14" Maple N25W 43.83' 14" Maple N25W 69.38' - exsisting Buckler BT - Good distance.		11
A. Description of original monument and accessories and/or subsequent restoration:  Oct. 20, 1850 Algernon Merryweather, DS section corner Sections 3,4 Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 In N47E 45 birch 28 N60W 22  Dec. 28, 1961 Billy D. Buckler, RLS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of comer evidence found and/or method applied in restoring or reestablishing corner.  Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument to identify.  Witnesses: 26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47' 24" Maple N25W 43.47' 24" Maple S56°W 69.38' - exsisting Buckler BT - Good distance.		
Oct.20, 1850 Algernon Merryweather, DS section corner Sections 3,4 Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 In N47E 45 birch 28 N60W 22  Dec.28, 1961 Billy D. Buckler, RLS "This corner was replaced 50 links south of fence corner and in intersection of roads to South, East and West. Position checks with good corneers to West.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Oct.30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument stamped to identify. Witnesses: 26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47' 24" Maple S56°W 69.38' - exsisting Buckler BT - Good distance.	A. Description of original monument and accessories and/or subsequent restoration:	13
Oct. 30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with illegible cap. Accepted iron bar and reset with Schoolcraft County monument.  C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. Schoolcraft County monument stamped to identify.  Witnesses: 26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47' 24" Maple S56°W 69.38' - exsisting Buckler BT - Good distance.	Sugar 16 in S73W 55 links Sugar 9 in S33E 15 links Sugar 16 In Dec. 28, 1961 Billy D. Buckler, RLS "This corner was replaced corner and in intersection of roads to South, East and West."	n N47E 45 birch 28 N60W 22  50 links south of fence
Schoolcraft County monument stamped to identify. Witnesses: 26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47' 24" Maple S56°W 69.38' - exsisting Buckler BT - Good distance.	Oct.30, 2000 Thomas P. O'Brien, PS found 3/4" iron bar with i	
Schoolcraft County monument stamped to identify. Witnesses: 26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47' 24" Maple S56°W 69.38' - exsisting Buckler BT - Good distance.		
Schoolcraft County monument stamped to identify. Witnesses: 26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47' 24" Maple S56°W 69.38' - exsisting Buckler BT - Good distance.		
Witnesses: 26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47' 24" Maple S56°W 69.38' - exsisting Buckler BT - Good distance.	C. Description of monument for comer and accessories established to perpetuate locating the po	osition of the corner:
Calsolitie Tost No E 50.0	Witnesses: 26" Maple N23°E 29.70' Road Sign S11°E 43.83' 14" Maple N25W 43.47'	THOMAS P. THOMAS P. O'BRIEN PROFESSIONAL SURVEYOR NO. 21274
Orange J. O. S. Manustra Contraction of the Contrac	Obour 7-015	W. OFESSIONALINE
Signed by Thomas P. O'Brien Date DEc.12, 2000	Signed by Thomas P. O'Brien Date D	
Surveyor's Michigan License No.	71774	
LIBER 4 PAGE: 375  FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, REVISED MAY 14,	Cultoyor o tallonigum Liberico	