LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

_			
For	COL	ners	in

Schoolcraft	Located In:	Corner Code #		
(County)	-			
1. Public Land Survey	T 43N R 16V T 44N R 16V T R			
2. Property Controlling in Section	S T R S T R			
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number	
4. Lot No. , Re-	corded Plat		A B C D E G H I J K	L M
above were in conformance with instructions of the United States a Court of Law and /or that the	74, Michigan P.A. of 1970, the coregulations and rules therefore as Department of the Interior, Bureau corner points mentioned in lines 3, rd of Land Surveyors or by a D	orner points mentioned in lines 1 and 2 required in the current manual of survey of Land Management or by a decree of 4 and 5 above were in conformance with decree of a Court of Law; established	2 4 7 8 9 10 11 9 5 9 7 10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	13—
on this certificate.	ners, all in the same town and r		10 30 29 28 27 26 11 12 31 32 33 34 35	36-
 A. Description of original re 	nonument and accessories and	d/or subsequent restoration:		

reestablished this corner (as well as corners B1, C1, D1, E1, G1, and H1) by single proportionate measurement between corners A1 and I1. Set aluminum county monument. 12" W.Pine N10E 15.40', 13" W.Pine S70E 23.52', 8" W.Pine N80W 28.60', 11" W.Pine S52W 29.57', carsonite post South 1.0'.

(F1) Quarter corner common to Section 4 T43N-R16W and Section 33 T44N-R16W. 1841 - Established by Wm.A.Burt Deputy Surveyor midway and on the Township Line between Section corners 40.00 chains east and west. Set post. Beech 10" N47E 34 links, Hemlock 16" N52W 13 links. 2007 - Michael Peterson PS

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (F1) The original post and accessories were not recovered. Found the 2007 monument and witnesses of record at an erroneous position, S89 deg. 32'08"W 269.63' from a position midway and on the Township line between monumented section corners E1 and G1, both of record. With Mr. Peterson's approval, the 2007 monument and witnesses were destroyed and defaced. I reestablished the position for the corner midway and on the curved Township line between Section corner E1 S89 deg. 28'34"W 2634.86' and Section corner G1 N89 deg. 28'07"E 2634.86'. All bearings stated in this paragraph are referenced to grid north, Michigan State Plane Coordinate System of 1983.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F1) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:

10" Maple N08E 10.8'

mrkd "1/4S NBT"

10" W.Pine N85W 34.05

do

9" Maple S05E 16.85'

do

8" Maple in clump S37E 23.84'

84' đo

Bearings are magnetic.

47483

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
No.
33986

Signed by	Stephen	1 Sm	oskal.	 Date	06/15/2011	
Surveyor's Mi	ichigan License No.	1	33986			