MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Tamarack B.T. bearing S 20° W 31 links, tree down but in excellent condition. Both faces plain.

Found Tamarack stump bottom bearing N 62° E 12 links for second B.T.

Found old blazed line both East and West of Corner.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED REGISTERED LAND SURVEYOR
Billy D. Buckler