LAND CORNER RECORDATION CERTIFICATE Filing Regularment of Act 74. Mich. P.A. 1970

	d beine.	A (todanal)									
For corners in Schoolcraft (County)	Located In:	Corner Code #									
1. Public Land Survey	T ^{46N} R_ T R_ T R_	15N 07									
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR S TR			Regist	er of	Deed	s Sta	ımp đ	. File	Numi	эег
			, ,	. В .	C D	E	F G	н	<u> I .</u>	J K	<u>L</u>
5. Private Claims			2	_ f	LĮ.	\bot	<u>l</u>	_ _ 3-	- :	<u> </u>	- - 1
		Apr 20 1998	3	_Ĺ	L.Ī	_	\square	_	\perp	- 	\perp
. Stephan J. Szyszkoski	in a fairl arrangen	, 19 do hereby state that u	ander 4	<u>_</u> ;	 	_ _	ا_وا	_1 <mark>0</mark> -	ֈֈ	<u> </u>	-12
requirements of D.A. 74 Michie	nan P.A. of 1970, the com	er points mentioned in lines 1 and 2 above w	rein _		\sqcup		\sqcup	\dashv		$\sqcup \!\!\! \perp$	4
conformance with regulations an United States Department of the	nd rules therefore as require interior, Bureau of Land & ed in Spec 3, 4 and 5 shows	ed in the current menual of survey instructions (Asnagement or by a decree of a Court of Law ar I ware in conformance with the rules of the Mici	orthe ond/or 6 higen _	18	- ;		6	15 1	+-1	-	-13 -13
Board of Land Surveyors or b recovered, found as expressed b	by a Decree of a Court (of Law; established, re-established, monume	nted, 8	 19 	— Ţ) 21 1	22_ 22	2] !3——	-24
NOTE: Not more than 2 co on this certificate.	mers, all in the same tow	vn and range, may be recorded	9 10	30	29	+	28-	_27_	 - 2	26	-25 -25
			11	 	+	+-	╂━╂	+	+	╁╌┼╴	+
			12	31	— 32	+	;) —	<u>—3</u> 4-	 -3	i '5 -	-36
			13	Щ.	Ш		L l			Щ.	_1_
A. Description of original m	onument and accessor	ries and/or subsequent restoration:	laton: "40	11 50	t Aus	rter :	eecti	00.00	ist	Hemlo	ck

A. Description of original monument and accessories and/or subsequent restoration:
(07) Quarter corner common to Sections 17-20. Corner established in 1850 by Guy H. Carleton: "40.11 Set quarter section post. Hemlock 17 S42W 41 links, Hemlock 22 W58W 17 links."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(D7) Original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner midway and on a line of mean true bearing between Section corners 2655.91' East and West. At the position for the corner, I placed a 1° ID. x 36° iron pipe capped with a 4° dia. cast aluminum HDNR tablet, appropriately stamped. Corner placed and mitnessed by T.Stark and M.Feldpausch, Newberry District Office.

C. Description of monument for corner and accessories established to perpetuate	locating the position of the corner:
(07) Set 1 pipe with 4 MDHR cap.	The state of the s
Blazed, scribed, and set measuring nails	STE OF MICH
in the following:	
5" Balsan West 9.15' "1/45 NBT"	STEPHAN J.
5" Maple N63N 28.05' "1/4S HBT"	# * SZYSZKOSKI
4" Maple MB9E 38.25' "1/45 MBT"	2 * LAND → B
6" Maple \$12M 11.3' "1/4\$ MBT"	SURVEYOR /
Placed a 4" squared and scribed cedar	No.
post 3 ft. NW of the wonument. Bearings	33986
are magnetic.	AND SUL
0. 1 1 1 1 1	Manager and the second
Signed by Steph Inghol	Date 7/29/98
	· · •
Surveyor's Michigan License No. 33986	

For the Michigan Department of Natural Resources - Forest Management Division