Cons. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

|                         | T. <u>46</u> N.R                    | Schoolcraft                 | COUNTY   |
|-------------------------|-------------------------------------|-----------------------------|----------|
| DESCRIPTION OF CORNER _ | Section corner for section          | ns <u>15(14</u><br>22  23   |          |
| CORNER MONUMENT         | 1" Iron pipe with 4" Bras           | s Cap.                      | <u> </u> |
| DATE MONUMENT PLACED AN | D WITNESSED <u>9-18</u> -6 <u>1</u> |                             |          |
| FITHESSES TO CORNER     | 10" Cedar (NBT S23)                 | SO4 <sup>O</sup> E 27 links |          |
|                         | 9" Cedar (NBT S15)                  | N72°W 14 links              |          |
| 123                     |                                     |                             |          |
|                         | AMD                                 |                             |          |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from cedar B.T. N52°E, 06 links in poor condition.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED -

REGISTERED LAND SURVEYOR

DATE December 29, 1961

Billy D. Buckler