0

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Schoolcraft (County)	Located in:	Corner Code #						
1. Public Land Survey	T <u>47#</u> R_ T <u>47#</u> R_ TR_	13N B9						
Property Controlling In Section Miscellaneous Property in Sec.	S TR_ S TR_ S TR_ S TR_			Register	of Deads	Stamp &	L File N	lumber
4. Lot No, Records. Private Claims	rded Plat		1 Å	B C	D E F	G H	I J	K L
conformance with regulations and United States Department of the i that the corner points mentioned	, in a field survey on _ in P.A. of 1970, the corner rules therefore as required riterior, Bureau of Land Mer in lines 3, 4 and 5 above w a Decree of a Court of low:	Hay 21 1996	ons of the 5 tw and for 6	19 2	5 - 4 - 9 - 16 - 17 - 16 - 17 - 17 - 18 - 9 - 28 - 19 - 28 - 18 - 18 - 18 - 18 - 18 - 18 - 18	3- -10- -15- -22- -77-	14-	13-24-
			11	31 3	233-		26	1

A. Description of original monument and accessories and/or subsequent restoration:
(C9) Corner common to Sections 19-20-29-30. Corner reestablished by proportionate measurement in 1955 by Billy D. Buckler, RLS. 1° pipe with 4" brass cap at corner with the following witnesses: 16" W. Pine stp. S15E 103 links, 26" M. Pine stp. H22E 70 links.

(89) Quarter corner common to Sections 19-30. Corner remonumented from an original 8T in 1955 by Billy D. Buckler, RLS. Corner was marked with a 1" pipe with 4" brass cap and the following: 16" Red Pine S63M 161 links, 16" Red Pine S29E 273 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(C9) Recovered the 1955 M. Pine stump witnesses. The corner monument itself was not found. Remonumented the corner at record bearing and distance from the two 1995 witnesses and marked two new accessories as described below. At the position for the corner, buried a 1" IOx 36" iron pipe capped with a 4" dia. cast aluminum MOWR tablet, appropriately stamped. The corner falls at the north side of a road. Corner remonumented by T.Stark and D.Lampela, Memberry.

(89) Recovered both 1955 witness trees, in good condition. The monument had presumably been moved by an unknown individual since 1955 as it was located to the west of the proper position. Removed the 1955 monument from it's erroneous position and placed it at record bearing and distance from the two 1955 witness trees. Marked 2 new witnesses as described below. Corner rewitnessed by T.Stark and

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(89) Set 1" pipe with 4" brass cap.

(89) Set 1" pipe with 4" brass cap.

(C9) Set 1" pipe with 4" MDNA cap. Blazed, scribed and set measuring nails in the following:

8" R. Pine N48W 62.9" "S19 N8T" Twin B" R. Pine M64E 33.8" "\$20 MBT" Placed a location post 15° south of the corner.

Blazed, scribed and set measuring nails in the following:

6" R. Pine \$50E 63.55 "1/45 NBT" 5" W. Pine M38E 68.5' "1/45 HBT" The 1955 witnesses: 24" R. Pine \$63# 106.4" 1/45

24" R. Pine S29E 180.1' 1/45 Placed a squared and scribed cedar post adjacent. Cor. lies north of E-N trail.

CAND SO

Bearings are magnetic.

Surveyor's Michigan License No 33986 OF MIE

STEPHAN J

SZYSZKOSKI

LAND

SURVEYOR