## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Filing Requirement of Act 74, Mich. P.A. 1970											
For corners in Schoolcraft	Located In:	Corner Code #									
1. Public Land Survey	· · · · · · · · · · · · · · · · · · ·	14N B13 14N C13									
Property Controlling in Section     Miscellaneous Property in Sec.	S TR_ S TR_ S TR_			Regis	ster o	Deed!	s Star	np & !	File 1	Numl	ber
4. Lot No, Record	ed Plat		1	A B	<u>c t</u>	3	F G	К	<u>;                                    </u>	ĸ	<u> </u>
<u></u>		Jul 03 1997	2	6-	+-:	· <del> </del>	<u> </u>	- š <del>-  </del>	2 	$\top$	- [ ]
Chamban 1 Ezwezkoaki		Aug 11 1997	3 				٠	_10			_12
Stephan J. Szyszkoski	in a field survey on _ P.A. of 1970, the corner	points mentioned in lines 1 and 2 above	. Ni enew e				<u> </u>	$\ddot{\perp}$	$\vdash$	$\dashv$	
conformance with regulations and r	ules therefore as required	nonement or by a decree of a Court of La	wand for 6	1,8-	┼;	<b></b> -!	¦•—	-15	\ <sup>1</sup>	┵	-13-
	- E 1 4 5 W	are in conformence with the rules of the Law; established, re-established, more	ARCHITECTURE	├┼	╁		<del>   </del>	+	一	+	$\pm$
recovered, found se expressed below:				19-	-			-22-		<u> </u>	-21-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			9	30	$\bot$	,	[ 2 <b>8</b> —	_27		<u>-</u>	_25
on this certificate.				+	-	-  -	╁┼	+	╂─┼	╁	+-
			12	2 3 1.	+	2	3 <sup>1</sup> 3	_3 <b>4—</b> 	-3 <sup>2</sup>	-	-36— 
I" pipe with 4" brass cap. W (C13) Corner common to Section	itnesses to corner: 1 ns 31-32 T47N-R14W an 3: "This corner was ey of this area. Mo	n good condition. Corner was pla O" J. Pine \$44W 27 links, 5" Sprud d Sections 5-6 T46K-R14W. Corner established, by double proportion original evidence at corner. Condess 20 links".	uce 566t 12 I r restored by nate measurem	iinks Mich ient,	igan I by-Fo	ept. o	f Con Divis	servat ion su	tion urvey	Survi	eyor
B. Description of corner evid	lence found and/or me	thod applied in restoring or reestable	ishing corner:	:							
(813) Found the 1953 monument condition, and at record bear in place and marked four new Mest. Corner recovered and r (C13) Found the 1953 monument condition. The 1954 bearing record and is in proper propo measurement rather than singl record. Accepted the monumen rewitnessed by T.Stark, Newbe	as described, a 1° I ing and distance from witnesses as describe emitnessed by T.Stark as described, a 1° I trees were not recovertion. MONR field not as a careful and farry District Office,	.D. iron pipe capped with a 4° d the two 1953 NBT's, now both cu d below. Measured to adjacent m. Newberry District Office, MDNR .D. iron pipe capped with a 4° bered. Distances west to quarter ites do not indicate why this corde enough information to determinithful determination of the posi MDNR. Centerline of a trail is	ia. MI Dept. t stumps with onumented Sec. rass MI Dept corner and to ner was rees ne if this i tion of the 41' South.	of Co h no v ction . of C o town tablis s a ty origin	corne onser ship hed b	e mark rs: 26: vation corner y doub phical rner.	table check error	East et, in es wel oportion	and good l with onation the Original control of the Or	2517 d th th e eLaMa	ne ater
(813) Found 1 pipe with 4 c Blazed, scribed, and set meas in the following: 6" M. Pine M72E 52.6' "1 B" M. Pine S70E 31.75' "1 8" M. Birch S15E 58.2' "1	rass cap. (c) suring nails Bla i/4S MBT 4" corner lies pos	ories established to perpetuate local (3) Found 1" pipe with 4" brass of sized, scribed, and set measuring the following: J. Pine S37M 65.2" "S6 MBT" J. Pine S28M 73.7" "S6 MBT" J. Pine S07M 64.45" "S6 MBT" J. Pine S16E 57.6" "S5 MBT" aced a 5" squared and scribed ced st adjacent. Bearings are magnet	nails		STE	PHAN SZKOS AND RVEY( No.	SKI DR				

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources - Forest Management Division

Signed by