For corners in

Schoolcraft	Located in:	Comer Code #	
(County)		33,113, 3333 11	
1. Public Land Survey	T <u>47N</u> R T R T R		 
Property Controlling     in Section     Miscellaneous	TR S_20 T_47# R S TR S TR	14W 11	 
Property in Sec.	š <u> </u>		<del></del>

Register of Deeds Stamp & File Number

A B C D E F G H I J K L M

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_

5. Private Claims \_

D8 May 12 1997 11 Feb 10 1997

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1												Γ
2	├-	<u>6</u>	<u> </u>	<u> </u>	<del> </del> -	<u> </u>	<b>-</b> ;	<u>}</u> —	<b>-</b> :	2	- 5	ļ —
3	L	L		<u> </u>		Щ		匚		_	_	
-	Ι.	<u> </u>				Ĺ		Į_		[		l.
4		<u> </u>	-	8 — i	$\vdash$	9	1	0— 1	<u> </u>	1	1	2-
5	_	_	-	H	$\vdash$			⊢	_	$\vdash$	-	_
6	L_1	. <b>e</b> —	1	<u></u>	_,	6—	1	l 5	_,	_	L,	L
- 1	٠	ĩ	ĺ	Ϊ	Ī	Ĭ	1	ľ	Î	i l	ì	ĭ
7	$\overline{}$							$\vdash$			$\overline{}$	
8	-1	9	Н	<b>9</b> —	<u> </u>	1	2	2	2	3	-2	4-
9					_			L		Ĺİ		
		].										
10	-3	·	-2	•	—2	8—	2 <sub>1</sub>	7—	—2	6-	<del> </del>	5—
11		Н		Н	_		Н	-	_			
12	1	ıЦ	3		3			_	1	ا 5	—3	<u>-</u>
		·			آ		Ĭ	1	آ	ĭ 7	آ	-
13												

A. Description of original monument and accessories and/or subsequent restoration:

- (DB) Center of Section 20. Corner not established in the original survey. Found no subsequent record.
- (11-Sec. 20) Southwest 1/16 corner, Section 20. Corner not established in the original survey. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(DB) Established the corner at the intersection of straight lines connecting opposite Quarter corners 2657.88' Morth, 2644.97' East, 2636.14' South, and 2640.62' West. At the position for the corner, I placed a 1" IDx36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. Corner placed and witnessed by T.Stark and O.Lampela, Newberry District Office. The corner is 100' east of a trail road.

(II-Sec. 20) Established the corner at the intersection of straight lines connecting opposite 1/16 corners. Only the 1/16 corners to the north (1320.13') and east (1321.20') are monumented at this time. At the position for the corner, I placed a 1" IDx36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. From the corner monumented, I found a cedar post, placed by persons unknown 25.8' South and 3.9' East. Corner placed and witnessed by T. Stark and D. Lampela, Newberry District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner (DB) Set 1" iron pipe with 4" HDNR cap. (11) Set 1 iron pipe with 4 HDNR cap.

12" J. Pine N39N 29.45" "CS BT" 10" N. Pine N40W 19.6" "SW1/16 8T" 6° J. Pine M87E 15.85' "CS 81" 4" N. Pine NI9E 5.55' "SW1/16 BT" 8° J. Pine S63E 9.25' "CS BI" 8" R. Pine N69E 30.1' "SW1/16 BT" 6" J. Pine S54N 30.6" "CS BI" 12" R. Pine S04E 57.5' "SW1/16 BT"

Placed a 5" squared and scribed cedar post adjacent. Bearings are magnetic. Placed a 5" squared and scribed cedar post adjacent. Bearings are magnetic.

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
No.
33986

Signed by Stephen J. Sansakoli Date 3/25/98
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources - Forest Management Division