SURVEY & REMONUMENTATION

AUG 0 5 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

RECORDED

Filing Requirement of Act 74, Mich. P.A. 1970 or corners in

93 DEC -6 AH IO: 50

iawassee (County)	Located In:	REMONUMENTATION Corner Code =##	
m.	7 50 D/F	L-11	
Public Land Survey 1 11	T 5N R 4E	F-11	38
	T R	<u></u>	
	T R	`	
(1965) - 지, 1967년 - 기 (1965)	T A		
Property Controlling	S T R		
In Section	S T A		
Miscellaneous	S		Register of
Property in Sec.	S T R		

REGISTER OF BEEDS وعاداته فالمنافئة وموساتك MY SSEE COUNTY MICH.

Deeds Stamp & File Number

, Recorded Plat Lot No. Private Claims

Norman C. Caldwell . in a field survey on . . 19 93 November hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the rrent manual of survey instructions of the United States Department of the Interior, Bureau of Land anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 gove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as xpressed below:

OTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

10/07/93

1/4 cor., Sec. 25 & 36, T5N-R4E

Wood post placed by J. D. Mullett, 1848 N54°E 33 lks. (21.78') 12" B. Oak S82°W 52 lks. (34.32') 8" Elm

Survey by E. F. Jostin, Co. Surveyor, 1898 Fnd. Huggins Corner S9 1/2°E 39 lks. (25.74') 6" Maple

Survey by E. J. McCombs, (C.P. Co.), April 1973 recorded in Surveys L. 1, pg. 484 Set 1/2" rebar

N85°W 44.0' SE'ly cor. N bridge abutment S85°W 43.32' NE'ly cor. S bridge abutment N75°E 89.8' PK Nail tele. riser pole N75°W 45.82' PK Nail 8" Walnut

L.C.R.C. by M.D. Pike, May 1973, recorded in Corners L. 1, pg. 109, Fnd. R.R. Sp 4 ke N80°W 45.83 3 12 11 Oak N70°E 89.78 4 Power Pole

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1/4 cor., Sec. 25 & 36, T5N-R4E

Corner has been destroyed by placement of 96" CMP in road. Reestablished corner position by using the NE & NW (R.R. Spike) corners of Sec. 36 used by McCombs Survey (C.P. Co.) per L. 1, pg. 484, Set a standard 20" Harrison marker as approved by the bisusesse County Peer Peyions Group, and is accepted. Shiawassee County Peer Review Group, and is accepted as a careful and faithful determination of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the nosition of the corner:

1/4 cor., Sec. 25 & 36, T5N-R4E

Corner has been destroyed by placement of 96" CMP in road. Reestablished corner position by using the NE & NV (R.R. Spike) corners of Sec. 36 as used by McCombs Survey (C.P. Co.) per L. 1, pg. 484, Set a standard 20" Harrison marker as approved by the Shiawassee County Peer Review Group, and is accepted as a careful and faithful determination of the position of the original corner

of the original corner.

N80°E 89.53' Fnd. PK & Washer NNW face tele. pole (R)

S65°E 69.98' Set N & T #12018 in North face 8" Elm

N58°W 63.91' Chis. "+" top center 96" CNP

S10°E 26.04' Chis. "+" top center 96" CMP

igned by Munning

OF MICHIO NORMAN C CALDWELL PROPESSIONAL BURYEYOR No. 12018

NOU 93

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAH. 28, 1971 REVISED MAY 14, 1975 REVISED JAH., 1983

DC

⊒rveyor's Michigan License No. .