MAY - 1 1995

## LAND CORNER RECORDATION CERTIFICATE

COMMISSION


RECORDED Filing Requirement of Act 74, Mich. P.A. 1970

Shiawassee (County)		Located in:		Corner Code #
1. Public Land Survey		T <u>71</u>	NR_1E R	(K-13)
		Υ	R	
		Τ	R	
2. Property Controlling	s	T	R	
in Section	s	T	R	
3. Miscellaneous	\$	T	R	
Property in Sec.	s	т	R	
4. Lot No	Re	corded P	lat	
5. Private Claims				

94 NOV 16 PM 3: 43 REGISTER OF DEEDS

SHIAWASSEE COUNTY MICH.

Register of Deeds Stemp & Flia Number



I, Mark L. VanRaemdonck, in a filed survey on October 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, remonumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subvequent restoration:
- 1.) Original: Robert Clark Jr., D.S. 1831

Monument: Wood post Accessories: Sugar 10 N41°W 56½ links do 12 N55°E 65 links

2.) J. Quine: Unrecorded. No date

Monument: Set R.R. splite stake flush with pavement
Accessories: "Iron pipe property corner stake N45°E
Road name sign post N40°W 38.4;
4" Liron corner fence post (Northwest corner) S67°E 77.0'
30" Walnut S30°15'E 63.2'

3.) N. Caldwell: L.C.R.C. Liber 2, page 687. 09/28/89

Monument: Found R.R. spike 0.3' below pavement raised flush with R.R. spike Accessories: South 1.5' Centerline East and West pavement East 5.0' Centerline gravel road North

East 5.0' Centerance 5.0' S70°W 131.2' Power pole 565°E 77.2' Steel fence corner post N55°E 48.6' Telephone pole

## APPROVED

County Remonumentation Peer Review Group 10/18/94 M.L.V.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories have been obliterated. Found R.R. spike and verified it to be the same as no.'s 2 and 3 above. I Interviewed J. Quine on 09/13/94 as to what methods he used to re-establish this corner location. He reviewed his field notes and explained that he had made measurements to several corners which he had verified from County Surveyor Records. I accepted this location as the faithful re-establishment of the original corner location. During excavation for placement of Harrison marker found %" x 12" square pin 3" below asphalt surface.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set standard Harrison marker stamped "REMON 24622" and witnessed by the following accessories:

N80°W 48.52' Fnd. P.K. and tag #11192 in East face util. pole S60°E 56.00' Set N&T in North face 15" Box Elder S75°E 98.14' Northwest corner 3" angle iron fence post N45°E 51.14' Set rerod and cap #24622

Surveyor's Michigan License No. 24622

Nov. 9, 1994