SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

) Of College in			
Shiawassee	Located in:	Corner Code	3026122 Page: 1 of 2
(County)			10/05/1999 02:
 Public Land Survey 	T_7N_R_2E_	<u>K-7</u>	Kaya Si mana - Gilammanos -
	TR T R		
	TR		<u> </u>
2. Property Controlling	sTR		Register of Deeds Stamp
In Section	s T R		& File Number
3. Miscellaneous	STR		— a Life Mullines
Property in Sec.	STR		
4. Lot No	, Recorded Plat		
5. Private Claims			

I, Mark L. VanRaemdonck, in a field survey on February 16, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1. Original, William Brookfield, D.S., November 1823. Access: Poplar 10 S26 W 95 Do 8 South 94

County Surveyor's Book, page 260. Field notes Owosso Township lists witnesses, no name, no date. Mon: Not given.

Access: S. Maple N381/4 °E 1/42 3/4 R. Cedar 4 S30 E 116 1/2

3. City Engineers Book (Large), page 28, E.S. Brewer, April 25, 1907. Mon: 3/4" Gas Pipe 24" long Access: Maple 12" S40 1/4"E 82.80" Maple 16" SS8 1/4"W 19:20 Maple 12" N26 1/4 "W 33:60"

4. City Engineers Book (Small), page 29, Same information as No. 3 above.

B. Description of corner evidence found and/or method applied in restoring or re-establishing comer:

Found 2" steel rod in monument box as referenced in No.'s 5, 6, 7 and 8 above. Found no conflicting evidence and accepted this location as the original corner position based on the best available evidence.


C. Description of monument for corner and accessories to perpetuate locating the position of the corner.

Replaced the 2' steel rod with a modified Shiawassee County Harrison marker morument. The monument is the top portion of a Harrison Marker that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt placed in the hole. This assembly that has been drilled and a 1/2" by 12" carriage bolt place

N25"W 35,24" Set N&T E. face util. pole N80"W 51.11" Chisled "+"E. Face S. leg Chemical Bank Sign N70°E 46.78' SVV corner conc. pad street light pole East 9.58' W. edge Water valve

Chipmen and M-21.

Signed by Mark L. Vallandon Surveyor's Michigan License No. 24622



APPROVED

County Remonumentation Peer Review Group

1 oct 99

MARK L

VANRAEMONCK

PROFESSIONAL

SURVEYOR

No.

24022

NO.

24022

Date <u>SEPT. 28, 1999</u>

JAN 16, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 City Engineers Book (Small), page 76, John F. Quine, September 12, 1963.
 Mon: 2" round iron rod, 0.1 feet West of center of monument box on North side of intersection.
 Access: NE cor. Geo. Thomas' 3rd Add.

South 491.82' SE cor. Geo. Thomas 3" Add. SE cor. Geo. Thomas' 3" Add. 1/4 post common to Sec. 23 and 24. South 2644.69'

6. M.D.O.T. Witnesses Card, Arden S. Pierson, May 1969.
Mon: Found 2" rod in mon. box 33" North of centerline of pavement.
Access: NSO"W 51.63" SE cor. fnd. hee. #1202
N30"W 76.37" NE cor. fnd. hee. #1202
West 24.00" Intersect. SW's (Back Edge)
East 43.00" Intersect. SW's (Back Edge)
N65"E 106.36" SW cor. Sunoco Gas Station

7. John F. Quine, L.C.R.C., recorded Liber 1, page 294, February 24, 1975. Mon: Found 2" iron rod in mon. box Access; Same as No. 6 above.

8. Russel Roon, L.C.R.C., recorded Liber 2, page 592, January 20, 1989. Mon: 2" rod in mon. box 33' North of centerline of pavement (M-21). Access: N65"E 106.38' SW cor. bldg. (Muffler Man) N65°W 20.16' Util: pole N15°W 52.44' 20" Maple S70°E 15.33' Center of telephone m.h. cover

3028122 Page: 2 of 2 10/05/1999 02:19P L-1 P-315

PENOMUMENTATION

SECTION