MAY - 1 1995

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

3

5

6

7 8

9 10

11

12

13

APPROVED

County Remonumentation

Peer Review Group

9/27/94 M.L.V

For corners 600MMISSION 94 NOV 16 PM 3: 41 Corner Code # Located in: Shiawassee REGISTER OF DEEDS (County) SHIAWASSEE COUNTY, MICH. 1. Public Land Survey 2. Property Controlling S in Section Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec.

I, Mark L. VanRaemdonck, in a field survey on October 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, remonumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

, Recorded Plat\_

- A. Description of original monument and accessories and/or subsequent restoration:
- 1.) Original: William Brookfield, D.S.

5. Private Claims\_

Monument: Wood post

S. Maple 14 N83°E 5 Accessories: 14 N74°W do

2.) O.M. Elliot: Book 24, page 75. 1956.

Monument: Not given

Consumer's sign post SE 32.5 Accessories: Walnut 12" SW 72.1 Iron sign post NE 41.85

3.) C.F. Smith: M.D.O.T. Dec. 1965. Monument: 1/2" iron cen. Morrice Road

T. pole N45°W 35.67' T. pole S36°E 56.49' Accessories: Road sign N60°E 44.80'

4.) J. Quine: L.C.R.C. recorded Liber 1, page 298. 2/9/73. Same as no. 3 above.

5.) M. VanRaemdonck: Survey recorded Liber 3, page 361. 3/21/80. Monument: Found 1/2" pipe Accessories: Same as no. 3 above.

6.) J. Matonich: L.C.R.C. Liber 2, page 546. 4/22/88.

Monument: 1/2" pipe

N60°E 44.8' Road sign

S60°E 53.9' N/disk NW face P.P. N70°W 51.06' N/disk SE face P.P. N80°W 22.15' S. edge S. leg sign post

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Description of corner evidence found and/or method approach to the description of corner evidence found and/or method approach to the description of corner evidence found and/or method approach to the description of the original corner location. Found a R.R. spike 0.15' East and 0.20' North of '/2" pipe 0.3' below surface while the best available evidence of the original corner location. Found a R.R. spike 0.15' East and 0.20' North of '/2" pipe 0.3' below surface while excavating for installation of Harrison marker.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set standard Harrison marker stamped "REMON 24622" and witnessed by the following accessories: Set standard marrison marker stamped NEW S65°E 53.94' Found N&T NW face utl. pole N75°E 47.94' S. edge stop sign post N30°W 81.13' Set N&T E. face 6" Maple N80°W 51.30' Set N&T S. face utl. pole

West 10.00' W. edge asphalt surface

Surveyor's Michigan License No. 24622

Date 101. 10,

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 197 REVISED MAY 14, 19 REVISED JAN., 19

VANRAEMDONCK SURVEYOR

MARK L
VANRAEMDO
LAND
SURVEYO
No.
24522
A LAND

A STATE LAND