MAY - 11995

LAND CORNER RECORDATION CERTIFICATE

RECORDED

1 2

For corners in

COMMISSION


Filing Requirement of Act 74, Mich. P.A. 1970

94 NOV 16 PM 3: 44

REGISTER OF DEEDS

Corner Code # Located in: <u>Shiawassea</u> (County) R <u>3E</u> (K-13)1. Public Land Survey 2. Property Controlling R in Section Miscellaneous Property in Sec. _, Recorded Plat 4. Lot No. 5. Private Claims

Register of Deeds Stamp & File Number



APPROVED

County Remonumentation

Peer Review Group 9/27/94 M.L.V.

WICHIGANNA SAMMINIMAN

OF WICHIGH

MARK L VANRAEMDONCK

LAND

SURVEYOR

1, Mark L. VanRaemdonck, in a filed survey on October 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, remonumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1.) Original: Joseph Wampler, D.S. Monument: Wood post

Accessories: Lynn 6 N8°E 21

Lynn 7 S36°E 4

2.) Ezra Mason, County Surveyor. Book B, page 91. Book A, page 159. CR 63, page 124 & 125. January 1861

Monument: Not given

Accessories: S. Maple 30 S411/2°E 1041/2 Butternut 5 S43°W 921/2

3.) O.M. Elliot: Book 49, page 43. June 1971

Monument: None given

Accessories: Road name sign post Northwest 51.15

Arrow sign post South 18.5 12" culvert Northwest 52.4

4.) Washtenaw Engineering Co., Inc. January 1974

Monument: R.R. spike

Accessories: Walnut 18" N30°W 82.45 Yield sign post N31°W 55.1'

Underground cable sign N32°W 56.7°

Road sign N45°W 51.22

Easterly post of directional sign S05°W 18.40°

5.) M. VanRaemdonck: L.C.R.C. recorded Liber 2, page 449

Monument: R.R. spike

Monument: N.N. spike
Accessories: N39°W 82.45' 18" Walnut
N31°W 55.10' Yield sign post
N32°W 56.7' Underground cable sign
N45°W 51.22' Road sign

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Mason harf the MASS 240. Original monument and accessories have been obliterated. Monument and accessories from 1861 survey by E. Mason have been obliterated. Found R.R. spike as referenced in no.'s 3, 4 and 5 above. Accepted this location as the best available evidence of the original corner position based on measurements to other corners. Excavation for Harrison marker provided no further evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Replaced the R.R. spike with a standard Harrison marker stamped "REMON 24622" and witnessed by the following accessories:

S40°E 48.79' Set N&T in N face utl. pole N40°E 48.28' Set N&T in W. face utl. pole N45°W 50.87' E. edge road name sign post S10°W 18.40' E. edge e. leg double arrow sign

N20°W 83.17' E. edge stop sign post

Signed by

Surveyor's Michigan License No. 24622

ROVED BY MICHIGAN-STATE BOARD OF LAND SURVEYORS JAN 18, 1971) REVISED MAY 14, 1975 REVISED JAN., 1983

IR