## SURVEY & REMONUMENTATION

MAY - 1 1995

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

For	corners	in

<u>Shiawassee</u>

(County)

COMMISSION

Corner Code #

94 NOV 16 PM 3: 45

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

2

3

5

6

7

8

9

10

11

1. Public Land Survey T 7N R 3E (M-13)2. Property Controlling in Section R R 3. Miscellaneous Property in Sec. R

Located in:

4. Lot No. \_, Recorded Plat

5. Private Claims

I, Mark L. VanRaemdonck, in a filed survey on October 21, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, remonumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1.) Original: Joseph Wampler

Monument: Wood post

Accessories: Sugar 7 N80°E 15 links

Ironwood 9 N60°W 12 links

2.) E. F. Joslin, County Surveyor: Book F, Shiawassee County Records Book of surveys, page 21. 04/9-10/1902

Monument: Iron stake at corner

Accessories: Double Elm 24" N681/4°W 64 links

3.) Washtenaw Engineering Co., Inc. January 1974

Monument: 1 1/4" iron pipe

Accessories: Walnut 18" Northerly 26.75' to nail Fence post N20°E 34.47' to nail Oak 26" N75°W 78.03' to nail

7' Easterly to fence line Northerly

(continued on reverse side)

APPROVED

County Remonumentation Peer Review Group 9/27/94 M.L.V

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories have been obliterated. Accessory from E. F. Joslin is gone. Joslin's notes call for an iron stake. Found 11/2" pipe as referenced in no.'s 3, 4 and 5 above. Accepted this location as the best available evidence of the original corner location based on measurements to other corners. During excavation to place Harrison marker, we found pieces of broken tile and several 3" to 4" diameter stones. We also found some scrap metal.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set standard Harrison marker stamped "REMON 24622" and witnessed by the following accessories:

North 27.27' Set N&T in E face 24" Walnut N35°W 37.68' Set N&T in E. face 10" Walnut

\$40°W 37.39' Set N&T in N. face 10" Ash \$70°E 70,00' Set N&T in N. face 10" Ash

OF MICHIG MARK L. VANRAEMDONCK LAND SURVEYOR No.

Signed by Man L. V.

Surveyor's Michigan License No. 24622

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

LIBER IR PG 102