1995 REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

For c	corners in Denmark	LAND CORNE	MONUMENTATION PROGRAM R RECORDATION CERTIF ment of Act 74, Mich. P.A	ICATE	VIRGINIA TUSCOI REGISTE	DEN P			SFCEIVEU	•
	Tuscola (County)	Located In:	Corner Code ##		A CO	9 PH	. #	77	-: 0:2	
1. F	Public Land Survey	T <u>12N</u> R <u>7E</u> T R T R	G-13		DEEDS DEEDS DEEDS	3:37	. K x ř		RECOKL	
3. N	Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R		Register of D	eeds Stam	p & Fil	e Nun	nber	r	
		corded Plat		— АВ	CDEF	: G Н	1 J	ĸ	L_	h
5. F	rivate Claims			2 6-	5 4	3]	-	_ .	
do he in line curre Mana above	ereby certify that under request 1 and 2 above were in our manual of survey instructions or by a decree of a continuance with a were in conformance with	in a field survey on Auguriements of P.A. 74, Michigan P.A. oconformance with regulations and stions of the United States Depart Court of Law and/or that the corner the rules of the Michigan Board of established, re-monumented, re-	of 1970, the corner points mention of rules therefore as required in ment of the Interior, Bureau of Li points mentioned in lines 3, 4 ar I Land Surveyors or by a Decree	ned 6 18 18 18 18 18 18 18 18 18 18 18 18 18	8 — 9 17 — 16 	10	1122	1 4 3 3 -	—12- —13- —24	

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Feb. 19, 1834 G.L.O. Notes Orange Risdon, D.S. Set Post Corner of Sections 33 & 34 Black Ash 12" N42E 32 Links Elm 10" N69W 25 Links

on this certificate.

expressed below:

May 4, 1971 Act 74 Form filed Page 22 Denmark Township by David T. Rowe, R.L.S. #11192. Found spike in asphalt. N75°W 107.62' nail in p.p., N70°E 53.64' SE cor. concrete hdwl., S80°W 148.39' nail in 24" oak.
May 9, 1978 Act 74 Form filed by Ronald C. Prevost R.L.S. #24612. Set 3/4" iron bar in place of nail found. S85°E 44.60' S.E. cor. S. hdwl. culvert, S60°E 41.20' N.W. corner W. hdwl. bridge, N45°E 47.22' N.W. cor. E. hdwl. bridge.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/4" iron bar 24" long. Accepted evidence found as the proper position of Corner G-13.

SIN VEY & ا المراقع المراجع المر المراجع المراجع

DEC V 1 1995

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Removed iron bar and placed concrete monument with standard brass cap stamped Corner G-13, T12N-R7E. Placed monument box over monument.

S55°41'E 41.25' West corner, Southwest concrete headwall.

N51°56'E 47.25' North corner, Northeast concrete headwall.

\$33°39'W 39.50' found 2" pipe.

N77°09'W 111.83' set T. C. Remon. tag & spike in NE face p. pole.

N29°19'E 20.7' physical centerline State Highway M-15.

Signed by 1

Date .

 $\Box \Box 0$ SURVINOR No. 23503

23503 Surveyor's Michigan License No. _

<u>APPROVED</u>

FORM APPROVED BY MICHIGAN STATE BURNO OF LAND SUBJECTORS, JAN. 28, 1978 REVISED MAY 14, 1975 REVISED JAN., 1983

