## Van Buren County Remonumentation Program

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Covert Township Section Corner 24,25	-
Van Buren Located In: Corner Code #	
(County)	
1. Public Land Survey  T2SR_17W	
2. Property Controlling       S TR	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L I
5. Private Claims	2 6 5 4 3 2 1
	3
in a field survey on 5/28, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	4 7 8 9 10 11 12 5 18 17 16 15 14 13 7 8 19 20 21 22 23 24
NOTE: Not more than 2 comers, all in the same town and range, may be recorded	9
on this certificate.	11
	12 31 32 34 35 36
	13
A. Description of original monument and accessories and/or subsequent restoration:	
M9, Post set by US Deputy Surveyor Wm Brockfield in April, 1827, witnessed to a Birch 1 N27½°W, 44 links. In 1902, County Surveyor WH Goss notes "found iron pipe with tile arc 91½ links. Goss measured the half mile west 2667.06. In notes accompanying a 1975 strod in stones and brick 2666.65 E of the quarter corner. Howard witnesses SW cor house \$10°E, 19.76; street sign, S45°W, 35.87; PK in S face 38" Maple, N30°W, 66.6; and an iron set a PK nail for the corner 48.84 north of an iron rod in mon box	urvey, Surveyor AW Howard found an iron N45°F, 103.25; nail in W face 10" Maple,
B. Description of corner evidence found and/or method applied in restoring or reestablishing cor	ner:
M9, Found rebar at surface 0.4 east of washing machine crank with stone around below bar in small mon box 40.18 south and ¾" pipe with remains of cap 48.93 south. Distance Accepted crank with stones around for corner location.	
THIS GOVERNMENT MONUMENT WAS RESTORED WITH THE APPROVAL OR REMONUMENTATION PEER GROUP OF SURVEYORS AT A MEETING HELD AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL	JOINE IT 1001, FAIR TO THE
C. Description of monument for corner and accessories established to perpetuate locating the p	osition of the corner
M9, Removed crank and set 20" Harrison monument in monument box in its place. With N34°W, 11.30, remains of PK nail(Zwar) S11°W, 40.18, 5/8" rod in small monument box N66°E, 103.18, SW corner house N42°E, 49.17, found nail in 20" Maple S18°E, 156.52, found nail in W face transformer pole S16°W, 112.33, NE edge hole in center of 30"diameter steel plate cap N46°W, 113.29, found nail in SW face transformer pole South, 48.93, Harrison monument at NW corner section 30, Bangor To	PROFESSIONAL SURVEYOR NO. 26453 on vertical CSP
Signed by Ony C. Bilow Date_	November 19, 1997
Surveyor's Michigan License No	