FEB 2 8 1994

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

missingerna

For corners in CORNADORO			
Wayne (County)	Located In:	Corner Code ##	
Public Land Survey	T <u>2S</u> R <u>11E</u> T R T R	E5	Compliance with ACT 345, P.A. 1990  APPROVED ON: 12-8-93-791.
Property Controlling     in Section	S T R S T R		WAYNE COUNTY REMONUMENTATION PEER GROUP COMMITTEE
3. Miscellaneous Property in Sec.	S T R		Register of Deeds Stamp & File Number
	Recorded Plat		
			3
	, in a field survey on <u>NOVe</u> equirements of P.A. 74, Michigan P.A		
in lines 1 and 2 above were	in conformance with regulations are tructions of the United States Depar	nd rules therefore as required	in the 0 18 17 16 15 14 13
above were in conformance v	of a Court of Law and/or that the corne with the rules of the Michigan Board re-established monumented re-	of Land Surveyors or by a Decr	ree of a

on this certificate.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

- Description of original monument and accessories and/or subsequent restoration:
- E-5 CORNER COMMON TO SECTIONS 8, 9, 16, 17

expressed below:

GLO SURVEY PERFORMED BY JOSEPH FLETCHER IN THE EARLY 1800'S. THE ACTUAL DATE AND TYPE OF POST SET WAS NOT

CITY OF DEARBORN ENGINEERING RECORDS (FIELD BOOK NO. 1047, DATED 1934). TYPE OF POST RE-SET/FOUND WAS NOT SPECIFIED.

MDOT WITNESS CARD (DATED 1964) FOUND 5/8" IRON ROD IN MONUMENT BOX.

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - FOUND 1° IRON ROD IN MONUMENT BOX FROM ABOVE REMAINING ACCESSORIES. THROUGH THE ANALYSIS OF FIELD MEASUREMENTS MADE TO VARIOUS FOUND MONUMENTATION POINTS IN THE SOUTHEAST 1/4 OF SECTION 8, BY SPALDING, DEDECKER, THIS POINT APPEARS TO BE THE ONE OTHER SURVEYORS HAVE RELIED UPON IN THE PAST. NO SURVEY KNOWN, E-5 RECORDED OR UNRECORDED, HAS WITNESSES SHOWN FOR THIS POINT. THIS POINT FITS LOCAL EVIDENCE FOUND IN THE NORTHWEST 1/4 OF SECTION 16, "SHEAHAN AND NAVIN'S SUBDIVISION". (L.19, P.60, RECORDED IN 1894) WITH A POSITIONAL TOLERANCE OF ± 0.2" (SEE RESEARCH DOSSIER). ALL EXISTING KNOWN EVIDENCE ANALYZED FAVORS THE CORRECTNESS OF THIS POINT.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**E**-5 CORNER COMMON TO SECTIONS 8, 9, 16, 17

FOUND 1 INCH IRON ROD IN MONUMENT BOX. SET 1/2' IRON ROD IN CONCRETE WITH WAYNE COUNTY REMONUMENTATION TAG AND LICENSE CAP #38121 DIRECTLY ABOVE 1' IRON ROD. THIS LOCATION IS ACCEPTED BY MYSELF AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF UTILITY POLE AZ. 66°, 75.38'; SET PK NAIL WITH TAG #38121 IN SE FACE OF UTILITY POLE AZ. 140°, 50.42'; NW CORNER BLDG. #5330

AZ. 150°, 51.76'; SET CUT "+" ON NORTH RIM OF STORM MANHOLE LOCATED IN CONCRETE SIDEWALK AZ. 235°, 82.71'; FOUND PK NAIL IN NORTHWEST FACE OF UTILITY POLE AZ. 303°, 98.85'; FOUND PK NAIL IN NORTHWEST FACE OF UTILITY POLE AZ. 345°, 161.53'; SET PK NAIL WITH WCR TAG IN WEST FACE OF UTILITY POLE

SURVEYOR SURVEYOR SET OF A MICHIGAN STATE BOARD OF LANGUAGE. JAN. 28. 1971 REVISED MAY 14. 1975 REVISED

Signed by Surveyor's Michigan License No.

38121 38121 GESSIONA REVISE REVISE REV

REVISED MAY 14, 1975 REVISED JAN., 1983