t ...

RECEIVED

## COMMISSION LAND CORNER RECORDATION CERTIFICATE 1993 DEC 29 AM 9: 41 Filing Requirement of Act 74, Mich. P.A. 1970

Fo	corners	in			Link	w Low	escale <u>is</u> a	116	اريرا	
		xford (Counly)	Located In:	Corner Code ##	WE	XFORD ( EGISTE)	<sup>⊄</sup> cour	ŧΤΥ.∃	MI	
1.	Public L	and Survey	T <u>22N</u> R <u>9W</u> T R T R T R	M-8						
2.	Property in Section	Controlling	S T R S T R							
3	Miscella		SR				_			
υ.	Property		S T R		Register o	of Deeds	Stamı	9 & F	ile N	lumbe
4.	Lot No	, Re	ecorded Plat			n c n		•		
						всо	E F	1	HI	JK
					2	6	<del>-</del>  - - - -		3	<u> </u>
					3			+		
					4	ļ _		1	0	_11
١, _	Richai	, 5				Ш				
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned							16-	١.	_	 —14—
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the						ľ	Τï		Ĭ	_; <u>4</u>
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5								1	$\Box$	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a						<del>9   2</del> 0-	21-	<b>─</b> ~	2	—23— I
	Court of Law; established, re-established, monumented, re-monumented, recovered, found as						++	+		_
exp	ressed be	fow:		•	10	3029-	- <del> </del> -2'8-	2	7	<u>—2</u> 6—
NO	TE: Not	more than 4 co	rners, all in the same town and	d range, may be recorded	11	<del>   -</del>				
	on f	this certificate.			12;	3132-	33-	3	4	35
					13		11.			L
Α.	Descript	tion of original m	nonument and accessories and	or subsequent restoration:						
	M-8)	1838 GLO Quarter Section post by John Brink, Deputy Surveyor Hemlock 11" S 14 1/2° W 40, Maple 9" N 5 1/2° W 20								
	M-8)	1971 Roser survey in Section 24: DNR monument, 24" Oak N 32° W 100.5, 14" Oak S 89° W 95.1 18" Oak, N 12° E 16.1 (Liber 2, page 980)								
	M-8)									
	M-8)	1990 Finnerty	survey: Liber 69, page 627	7, DNR monument						
₿.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:									
	M-8)	1/4 Section corner common to Sections 24, and 19, T22N, R8W Found DNR monument±58' West of centerline of a North-South road. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.								
				j [	Peer Group Date:	Reviewe - 29 - 9	d and	Аррі	ove	d
				Ē	Luker I	1.41	elay	<u>,                                     </u>		_ _
				11	lichard D. Wild	ux, Wexto	ra Çayı	nty Su	rvey	or

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard DNR monument on 1" pipe

S 69° E - 2.90 - 22" Oak S 78° W - 14.80 - 5" Maple in clump N 15° E - 17.05 - 20" Oak stump

S 25° W - 5.16 - 8" Maple in clump N 29° W - 100.88 - 30" Oak

N 89° W - 95.44 - 16" Oak N 15° E - 17.05 - 20" Oak stump

WILCOX

[[] [] [] [] [] [] [] [] [] [] [] [] []
Signed by Reway 1:00,000
Surveyor's Michigan License No. 33989

\_\_ Date \_\_11/29/93