RECEIVED

MAR 3 1 1994

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1993 DEC 29 AM 9: 43

Linda	Louis	gåne	ller
WEXF	ORD @	COUNT	TY. MI
REG	ISTER	OF DE	EDS

Fo	r corners in MANGESTO	Filing Require	ement of Act 74, Mich. P.A.	1970	¥	inde	. .	У.,	أم مع	2	20	2.		
	Wexford (County)	Located In:	Corner Code ##		Ø1°	WE	XFO Egis	RD 4	o col	u) II	TY. I	М		
1.	Public Land Survey	T <u>23N</u> R <u>9W</u> T R T R	M-7											
2.	Property Controlling in Section	S T R S T R												
3.	Miscellaneous	S T R		Regist	er o	f De	eds	Sta	mp /	R F	ile 1	Mun	nbe	r
	Property in Sec.	S T R												•
4.	Lot No, R	ecorded Plat			A	вс	. D	E	f i	G I	н 1	ı J	ĸ	L
5.	Private Claims					ΪŤ	Ť	Ť	$\dot{1}$	Ĭ	ΪŢ	Ť	Ì	
				2	Γ.	6 I	— 5 — I	+	4	3	i –	— 2 	-	_
				3			+	+	${}$	М				
	Dishard Wilson	Novem	shor 11 02	4		7	— 8 — I	十	9 —	1	ì		1	
l, _	horeby certify that under rec	in a field survey on <u>NOVEII</u>	nber 11 , 19 93 of 1970, the corner points mention	ad			+	+	+	H	\vdash			
in	lines 1 and 2 above were in	conformance with regulations ar	nd rules therefore as required in t	he ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	Ι'	B —	1'7- 1	+	16-	1	5	1	4	\vdash
cu	rrent manual of survey instru	ctions of the United States Depar	tment of the Interior, Bureau of La	nd ⁷		-	+	+	+	\vdash	\vdash	\vdash		
			er points mentioned in lines 3, 4 and of Land Surveyors or by a Decree o	fa	,	9	2 ¹ 0	+	2 ¹ 1—	<u> </u>	2-	-2	3	
Co	ourt of Law; established, re	e-established, monumented, re-	monumented, recovered, found	as g	'		+	+	+		\vdash			\vdash
	pressed below:			10	' 3	io	2 ¹ 9	+	28	-2	7	2	6	\vdash
NC	OTE: Not more than 4 co	orners, all in the same town a	nd range, may be recorded	11	\vdash	\vdash	+	+-	-	-	-1	Н	H	
	on this certificate.			12	; -3	<u> </u>	—3 ¹ 2-	+	33-	 3	4	-3	5—	H
				13	ــــا ،	ш		—		L	<u> </u>	ш	Ш	L
A.	Description of original n	nonument and accessories an	d/or subsequent restoration:											
	M-7) 1972 Wilcox 8	survey in Section 18, T23N, R	aty Surveyor, Beech 10" S 78° 8W, Liber S-1, page 47, Found	1/2" Iron	and	cap	S 50	o° v	66 V 30).23	3			
	Road sign, S 5 M-7) 1973 Roser su	50° E 353.36 road sign, N 45° rvey in Section 13: 1/2" Iron	W 40.98 underground tele rise in center of road intersection as	r N 45°E recovered	63.6 I by	50 4' Wile	' Pir cox	ie tele	pole	ı N				

- 1977 Wilcox survey in Section 13: Liber 1, page 549, 1/2" Iron S 50° W 30.23 road sign, S 50° E road sign M-7)
- 35.36, N 45°W tlel riser 40.98, N 45° E 4" Pine 63.60 1993 Wade-Trim survey in Section 13: 1/2" Iron, N 38" E 12" Red Pine 63.66, N 66° W 4" Twin Elm 64.68, S M-7)
- 50° W road sign 42.65, S 47° E face phone ped. 36.57 Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Section corner common to Sections 13, 24 and 18, 19, T23N, R8W M-7Found Iron & cap in centerline of North, South, East West roads. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Peer Group Reviewed and Approved

Richard D. Wilcox, Wexford County Surveyor

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - 5/8" x 36" Iron with Wexford Co. brass cap stamped: SE 13, PS 33989, 1993 M-7)

N 41° E - 63.66 - 12" Red Pine

N 63° W - 64.68 - 4" Twin Elm

S 44° E - 36.57 - SW corner face phone pad

\$ 56° W - 52.75 - 4" Elm

WILCOX LAND SURVEYO

	0111	7
Sanad bu	William Will	Vilay
Signed by	- Colored O	

Date _11/29/93

Surveyor's Michigan License No. 33989

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED JAN., 1983

LISER

04 PAGE 204