LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in RECEIVED Wexford Located In: Corner Code # 1996 DEC 13 PM 3: 32 T 23N R 10W 1. Public Land Survey WEXFORD COUNTY, MI REGISTER OF DEEDS T 2. Property Controlling _T __ __T_ in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section __ , Recorded Plat_ 5. Private Claims George D. Smith, in a field survey on July 23 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: GLO Quarter Section Post by John Brink, Deputy Surveyor, Beech 10 N 19° E 32, Cherry 12 N 59° W 24 1908 D.E. Teed Survey, Liber 1, Page 295 found stake and stone tele. pole S 42 3/4° E 26', elm 24 S 32° W 94.1' WCRC Bk. 30, Page 2, 15" Elm N 45° W 52.17', 33" Maple S 45° W 53.87', T.P. N 70° E 34.00'. 1955 WCRC witnesses, found 1" iron rod in concrete no witnesses given 1967 1968 Griffin RLS# 13584 LCRC, Liber I, Page 440 found 1 1/8" x 24" iron encased with cone. replaced with 5" x 3' cone. post with 3" brass disk stamped T23N-R10W, S32, S33, S5, S4, T22N-R10W 1968, RLS #13584 "x" in top of stone (15" x 15" x 24") N 50° E 77.26', 16 Penny spk. in sign post S 79° E 68.30', 16 penny spk. in tele pole S 2° E 62.95', NE corner of concrete block cabin S 65° W 123.60'. 1987 Wilcox Certificate of Survey by J.L. Wilcox, RLS #14102, Liber 2, Page 355 corner found no description or witnesses given B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: E-13) Found U.S.F.S. Conc. Mon. Centerline Road East-West and Northerly extended. This corner is accepted as the best available evidence of the position of the original corner being the section corner common to Sections 32 and 33, T23N, R10W and Sections 5 and 4, T22N, R10W BUNVEY & FEMONUMENTATION Peer Group Reviewed and Approved Date: 14 Nov 96 May 2 o 1997 al a ittly MARKET COMMENTS Richard D. Wilcox, Wexford County Surveyor C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: E-13) U.S.F.S. Concrete Mon. with 3" Disk stamped: T23N-R10W, S32, S33, S5, S4, T22N-R10W, 1968 RLS#13584 OF MICHIGAN S65°W - 123.53' - NE Corner Conc. Blk Cabin N45°W - 54.80' - 4" Elm N02°E - 71.55' - Nail in top of guard rail post GEORGE D S40°W - 55.17' - 48" Maple SMITH S62°E - 80.95' - Corner fence Post CHCENE **PROFESSIONAL** SURVEYOR No. 39098 POFESSION _Date 11-21-96

4 PAGE 441

LIBER

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1963